Exhibit 75



Cordless Electric Lawn Mowers Recalled Due to Fire Hazard; Made by Hongkong Sun Rise Trading



Kobalt 40-Volt max dual blade lawn mower













Name of Product:

Cordless electric lawn mowers

Hazard:

The circuit board in the **cordless electric lawn mower** can short circuit and catch fire, posing a fire hazard to users.

Remedy:

Repair

Recall Date:

May 26, 2017

Units:

About 28,000

Consumer Contact

Hongkong Sun Rise Trading toll-free at 888-266-7096 from 9 a.m. to 5 p.m. ET any day or online at www.greenworkstools.com and click on "Important Safety Notice" at the bottom of the page for more information.

Recall Details

Description:

This recall involves Kobalt and Greenworks brands of cordless electric walk-behind lawn mowers. The recalled lawn mowers have four wheels (two smaller ones in the front and two larger ones in the back), a 40-volt max lithium ion battery and a deck width of 20 inches. Both models have a large label on the rear bag door area with a serial number, model number and date code. The Kobalt brand mowers also have an item number on the label. "Kobalt" or "Greenworks" is printed on the side of the bag. The following models are included in the recall.

Brand	Product	Colors	Model Number	Item Number	Date Codes
Kobalt	40-volt max cordless dual-blade push lawn mower	Blue and black	KM2040X- 06	506586	04/14/14 to 05/14/15
Greenworks G-MAX	40-volt twin force	Green and	25302	N/A	04/10/14 to

cordless black 07/17/15
electric
push lawn
mower

Remedy:

Consumers should immediately stop using the recalled lawn mowers, remove the battery and contact Hongkong Sun Rise Trading for a free repair.

Incidents/Injuries:

The firm has received 12 reported incidents with the recalled lawn mowers including 5 reports of fires. No injuries have been reported.

Sold At:

Lowe's and other retailers nationwide and online at Amazon.com, Lowes.com and other websites from May 2014 through July 2016 for about \$350.

Manufacturer(s):

Hongkong Sun Rise Trading Ltd., of China

Distributor(s):

Sunrise Global Marketing, of Mooresville, N.C.

Manufactured In:

China

Recall number:

17-168