

U.S. Consumer Product Safety Commission

CPSC Stands for Safety

China Product Hazard Monthly Summary Bulletin

May 2022

2022 年五月

The China Product Hazard Monthly Summary Bulletin advises Chinese manufacturers of the most commonly occurring hazards posed by products they produce, such as excessive lead levels in children's products, choking hazards caused by children's upper outerwear garments with drawstrings, and others. More information on specific cases listed below is available by clicking on the link or going to: CPSC's Recalls page.

《中國產品危害每月小結簡報》的目的是提示中國廠商注意一些他們生產的產品最常出現的危害,諸如兒童產品含鉛過多,兒童上衣外套帶拉繩引起的窒息等問題。簡報中相關個案的詳細情況,可以點擊 CPSC 的召回頁面,查看公告全文。

Screws can become loose and/or detach from the xylophone component of the activity tables, posing a choking hazard to young children. 活動桌上的揚琴螺絲會鬆脫或與揚琴脫離,對幼兒構成氣管堵塞危害。 The children's pajamas fail to meet the U.S. federal flammability standards for children's sleepwear, posing a risk of burn injuries to children. 兒童睡衣不符合美國聯邦兒童睡衣阻燃標準,對兒童構成燒傷風險。 A software malfunction in the electrical system of the hoverboard can continue to provide assistance to the motor, causing continued momentum, when the rider is not activally controlling the hoverboard paging fall and injury becards.
活動桌上的揚琴螺絲會鬆脫或與揚琴脫離,對幼兒構成氣管堵塞危害。 22-749 The children's pajamas fail to meet the U.S. federal flammability standards for children's sleepwear, posing a risk of burn injuries to children. 兒童睡衣 不符合美國聯邦兒童睡衣阻燃標準,對兒童構成燒傷風險。 22-135 A software malfunction in the electrical system of the hoverboard can continue to provide assistance to the motor, causing continued momentum, when the rider is
22-749The children's pajamas fail to meet the U.S. federal flammability standards for children's sleepwear, posing a risk of burn injuries to children.兒童睡衣不符合美國聯邦兒童睡衣阻燃標準,對兒童構成燒傷風險。22-135A software malfunction in the electrical system of the hoverboard can continue to provide assistance to the motor, causing continued momentum, when the rider is
children's sleepwear, posing a risk of burn injuries to children. 兒童睡衣 不符合美國聯邦兒童睡衣阻燃標準,對兒童構成燒傷風險。 22-135 A software malfunction in the electrical system of the hoverboard can continue to provide assistance to the motor, causing continued momentum, when the rider is
兒童睡衣 不符合美國聯邦兒童睡衣阻燃標準,對兒童構成燒傷風險。 22-135 A software malfunction in the electrical system of the hoverboard can continue to provide assistance to the motor, causing continued momentum, when the rider is
A software malfunction in the electrical system of the hoverboard can continue to provide assistance to the motor, causing continued momentum, when the rider is
provide assistance to the motor, causing continued momentum, when the rider is
not actively controlling the hoverhoord, peoing fell and injury bezonds
not actively controlling the hoverboard, posing fall and injury hazards.
懸浮滑板 的電子系統由於軟件不良,在騎行人沒有積極控制懸浮滑板時會繼續給馬達
提供動力,致使滑板由於慣性繼續滑行,構成跌倒和受傷危害。
22-748 The coffee cup can crack or break when hot water is poured into it, posing a burn
hazard.
咖啡杯在熱水灌入時會裂開或斷裂,構成燒傷危害。
22-129 The children's robes fail to meet U.S. federal flammability standards for children's
sleepwear, posing a risk of burn injuries to children.
兒童睡袍 不符合美國聯邦兒童睡衣阻燃標準,對兒童構成燒傷風險。