ENVIRONMENTAL HEALTH & ENGINEERING

072909 FL01

Environmental Health
& Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

Date 7/29/09

Field Technician(s) MAF, TMM, WEC

House Address (b)(6)

General Weather Description Hot Sunny

1. Questions for the home Owner

1) Interviewed YES NO

2) Age of the House

3 years + construction

3) Estimated Floor Area

≈ 2000 1980 sq feet under AC not including garage or porch

4) Was as there any demo's to the house? If so, when? Please explain.

NO

5) Has there been any fire in the building?

NO

6) Any pesticides/herbicides been applied around the building or in the yard? If yes, when and which chemicals?

Termite outdoors no pest spraying indoors

7) Has there been any recent painting/staining done in the home?

Chair rail 4-5 months ago painting under rail

Last year added tile to laundry room

8) Has any work been done on the AC system since construction?

Adjusting 6 mo checkup

9) Are all the AC system components original?

Yes

10) What is the age of your refrigerator?

new w/ house

11) Has any piping been replaced in the home?

NO

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many?

2) Number of rooms

7 2 bedrooms, kitchen, laundry great room

3) Above grade Construction

Exterior concrete block

Wood Frame Concrete Stone Brick

4) Basement

Full Crawlspace Slab Other _____

5) Foundation

Concrete Cinder Block Stone Other_____

6) Garage

YES NO

If yes, Attached Detached

If yes, Used for Car Parking No Car

If yes, Any gas-powered equipment or cans of gasoline/fuels stored?

NO

YES NO

7) Type of HVAC System

(b)(3):CPSA Section 6(b) compressor outside

8) Primary Type of Fuel

furnace stove water heater

Natural Gas Fuel Oil Kerosene Electric

Propane Solar Wood Coal

9) Water Supply

Public Well Other _____

10) Sewage

Public Septic Leach Field Other _____

11) Attic

Finished Unfinished

3. Interior Characteristics

1) Any odors upon entering the building?

Yes No

If yes, describe _____

2) Fireplace

Yes No

3) Floors

Hardwood Carpet All tile

4) Walls

Wall Paper Paint Skim Coat Textured

5) Ceiling

Wall Paper Paint Skim Coat Textured

House Address (b)(6) Page 1

GUEST BEDROOM AREA



House Address _____ Page 2



House Address _____ Page 3



House Address _____ Page 4



House Address _____ Page 5



House Address (b)(6) _____ Page _____



VOC SAMP FIELD DATA

Page __ f ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 7/29/09

Home Address: (b)(6)

Project#: 16312

Field Person(s): TMH MAF, WEC

SAMPLE ID	CANISTER ID	FLOW CONTROL ID	GAUGE ID	FLOOR	LOCATION	SAMPLE TYPE	GAUGE PRESSURE START	START TIME	GUAGE PRESSURE END	END TIME	NOTES
99431	AC1096	FC00164		1	GREAT ROOM	S		9:13			
99432	AC1117	FC0545		1	DUPLICATE 99431	D		9:13			
99433	AC0917	FC0504		G	OUTDOORS	S		9:14			
99434	AC0080	FC00502		1	GUEST ROOM			9:14			
99435	AC00663	FC00557		1	MASTER BEDROOM			9:13			

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CDSC

Home Address: (b)(6)

Field Person(s): TNM, MAF, WEC

Date: 7/29/09

Project#: 16512

ROTA ID #: R06

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
99417		GREAT ROOM	INORGANICS	S	G11	.51	913	.42		201	
99418		DUPLICATE 99417		D	G16	.50	913	.41		200	
99419		OUTDOORS		S	G21	.50	914	.46		202	
99420		GUEST ROOM		↓	G09	.50	~~914~~	.41		160	
99421		MASTER BED		↓	G13	.51	913	.47		205	
99422		MB									
99423		FIELD BLANK									

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMH, WEC, MAF

Date: 7/29/09

Project#: 16512

ROTA ID #: R06

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
99410		GREAT ROOM	ORGANICS	S	G15	.51	913	.41	12:35	200	92
99411		DUPLICATE 99410		D	G07	.51	913	.47		199	
99412		OUTDOORS		S	G06	.50	914	.45		202	
99413		GUEST ROOM			G14	.51	914	.45		206	
99414		MASTER BED			P62	.51	913	.45		205	
99415		MB									
99416		FB									
~~99417~~		~~FB~~		TMH							INVALID LINE

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM, MAF, WEC

Date: 7/29/09

Project#: 16512

ROTA ID #: R06

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
99424	1	GREAT ROOM	ALDEHYDE	S	G04	.51	913	.51		200	
99425	1	DUPLICATE 99424		D	G17	.50	913	.48		202	
99426	G	OUTDOORS		S	G10	.51	914	.45		202	
99427	1	GUEST BEDROOM			G05	.50	914	.50		207	
99428	1	MASTER BED			G08	.50	913	.50		206	
99429		MB									
99430		FB									

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Page __ f ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Home Address: (b)(6)

Field Person(s): TMM, MAF, WEL

Date: 7/29/09
Project#: 16512

ROTA ID #:

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
99517		LIVING ROOM		AIR	G#69		1532				30 sec GRAB
99518		DUPLICATE 99517					1533				
99519		OUTDOORS					1534				
99520		GUEST BED					1535				
99521		MASTER BED					1536				

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page 1 of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CDSC

Home Address (b)(6)

Field Person(s): THH, WEC, MAF

Date: 7/29/09
Project#: 16512

XRF Serial #: 10755
XRF Scan Time: START 950

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	TIME	XRF Reading	NOTES
4	1	FOYER	N	4 FEET ↑	TEXTURED	FOYER 1	SCAN	954	269	
5		↓	N	2 FEET		↓		1005	352	
6		↓	E	6 FEET		FOYER 4		1006	406	
7		FOYER (SOCKET)	E	18"		↓		1007	390	
8		FOYER	W	4 FEET		FOYER 2		1008	410	
9		↓	W	2 FEET		FOYER 2		1009	331	
10		↓	S	5 FEET		FOYER 3		1010	387	
11		↓	S	2 FEET		↓		1011	241	
12		OFFICE	E	6 FEET		OFFICE 4		1012	421	
13		↓	E	2 FEET		↓		1013	383	
14		↓	S	4 FEET		OFFICE 3		1014	256	
15		OFFICE (SOCKET)	S	18"		↓		1016	407	
16		OFFICE	N	6 FEET		OFFICE 1		1017	270	
17		↓ (SOCKET)	N	18"		↓		1018	340	
18		↓	W	6 FEET		OFFICE 2		1019	370	
19		HALL	N	6 FEET		HALL 1		1020	541	
20		↓	N	2 FEET		HALL 1		1022	458	
21		↓	S	6 FEET		HALL 2		1024	364	
22		↓	S	2 FEET		↓		1025	696	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page 2 of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Home Address: (b)(6)

Field Person(s): THM, WEC, MAF

Date: 16312
Project#: 7/29/09

XRF Serial #: 10755
XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	TIME	XRF Reading	NOTES
23	1	DUPLICATE 22	S	2 FEET	TEXTURED	HALL 2	SCAN	1025	719	
24		KITCHEN	E	7 FEET		KITCHEN 4		1027	256	
25		↓	E	6 FEET		KITCHEN 4		1028	203	
26		DUPLICATE 25	E	6 FEET		↓		1029	178	
27		KITCHEN (SOCKET)	E	18"		↓		1030	228	
28		↓	W	4 FEET		KITCHEN 2		1031	315	
29		(SOCKET)	W	18"		↓		1032	276	
30		↓	N	7 FEET		KITCHEN 1		1033	255	
31		DUPLICATE 30	N	7 FEET		↓		1034	287	
32		LIVING ROOM	N	6 FEET		LR 1		1035	367	
33		↓	N	2 FEET		↓		1036	176	
34		(SOCKET)	N	18"		↓		1038	317	
35		↓	E	6 FEET		LR 4		1039	223	
36		(SOCKET)	E	18"		↓		1040	267	
37		↓	E	6 FEET		↓		1041	227	
38		↓	S	7 FEET		LR 3		1042	234	
39		DUPLICATE 38	S	7 FEET		↓		1043	256	
40		LIVING ROOM	W	5 FEET		LR 2		1044	207	
41		(SOCKET)	W	18"		↓		1045	275	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): THM, MHF, WCL

Date: 7/29/09
Project#: 16512

XRF Serial #: 10755
XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	TIME	XRF Reading	NOTES
42	1	LIVING ROOM	W	6 FEET ↑	TEXTURED	LR2	SCAN	10:47	260	2
43		↓	W	2 FEET		LR2		10:48	303	
44		LAUNDRY	W	5 FEET		L4		10:50	888	
45			W	5 FEET		↓		10:51	261	
46			W	7 FEET		↓		10:52	890	
47			N	6 FEET		L3		10:54	219	
48		DUPLICATE 47	N	6 FEET		↓		10:55	245	
49		GARAGE	S	6 FEET		G1		10:56	794	
50		↓ (SOCKET)	S	3 FEET		↓		10:57	280	
51		↓	S	5 FEET		↓		10:58	218	
52		GUEST BED	E	5 FEET		GB2		10:59	252	
53		↓ (SOCKET)	E	18"		↓		11:00	329	
54		↓	N	6 FEET		GB3		11:01	203	
55		↓ (SOCKET)	N	18"		↓		11:02	265	
56		↓	W	5 FEET		GB4		11:03	375	
57		DUPLICATE 56	SW	↓		↓		11:04	380	
58		GUEST BED	S	4 FEET		GB1		11:05	341	
59		GUEST BED CLOSET	S	2 FEET		GBC1		11:06	176	
60		GUEST HALL	E	5 FEET		GH2		11:07	238	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page 4 of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address (b)(6)

Field Person(s): TMM, WCC, MAF

Date: 7/29/09
Project#: 16812

XRF Serial #: 10755
XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	TIME	XRF Reading	NOTES
61	1	GUEST HALL	E	2 FEET	TEXTURED	GH 2	SCAN	11:07	196	
62			W	2 FEET		GH 4		11:08	314	
63			W	5 FEET		GH4		11:09	219	
64			S	2 FEET		GH 1		11:10	292	
65			S	2 FEET		GH1		11:11	268	
66		GUEST BATH	N	7 FEET		GB 3		11:12	316	TILE COVERING 6' ↓
67			E	7 FEET		GB2		11:13	281	
68		MASTER HALL	S	5 FEET		MH 1		11:14	328	
69		(SECRET)	S	18"		MH1		11:15	257	
70		MASTER HALL	N	3 FEET		MH		11:16	285	
71		MASTER BATH	W	5 FEET		MBATH 4		11:17	276	
72			E	5 FEET		MBATH 5		11:18	356	
73			N	5 FEET		MBATH 3		11:20	300	WALL 1 TILED 7 FEET
74			E	5 FEET		MBATH 2		11:21	341	
75		MASTER CLOSET LEFT	W	4 FEET		MCL 4		11:22	406	
76			S	2 FEET		MCL 1		11:23	175	
77		DUPLICATE 76	S	2 FEET		MCL1		11:24	166	
78			N	3 FEET		MCL3		11:25	245	
79		MASTER CLOSET RIGHT	E	4 FEET		MCR2		11:26	347	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCA[illegible] IELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMH, [illegible], [illegible]

Date: 7/29/09
Project#: 16512

XRF Serial #: 10765
XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	TIME	XRF Reading	NOTES
80	1	MASTER CLOSET RIGHT	S	6 FEET	TEXTURED	MCR3	SCAN	1207	447	
81		↓	N	2 FEET		MCR1 ~~MBD3~~		1208	1053	* CORE SAMPLE
82		MASTER BED	N	5 FEET		MBED3		1209	608	
83		(SOCKET)	N	18"		MBED3		12[10]	412	
84		MASTER BED	W	5 FEET		MBED4		12[11]	395	
85		DUPLICATE 84	W	5 ↓		MBED4		12[13]	388	
86		(SOCKET)	N	18"		MBED3		12[14]	357	
87		MASTER BED	W	5 FEET		MBED4		12[15]	381	
88		↓	N	↓		MBED5		12[16]	349	
89			W	5 FEET		MBED6		12[17]	477	
90			S	2 FEET		MBED1		12[18]	256	WALL 1
91			E	6 FEET		MBED2		12[19]	309	
92		↓	E	2 FEET		↓		12[20]	363	
93		DUPLICATE 92	E	↓		↓		12[21]	390	
94		MASTER BED CEILING	—	CEILING		MASTER BC		14[02]	278	
95		↓	—	↓		↓		14[03]	324	
96			—					14[04]	256	
97			—					14[05]	—	INVALID
98	↓	↓		↓	↓	↓	↓	14[06]	267	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CBC

Home Address: (b)(6)

Field Person(s): THM, MAF, NEC

Date: 7/29/09
Project#: 16512

XRF Serial #: 10755
XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	TIME	XRF Reading	NOTES
99	1	MASTER HALL	—	CENTER	TEXTURED	MHC	SCAN	14:08	293	
100		MASTER BATH	—			MBC		14:09	205	
101		MASTER BATH	—			MBC		14:11	323	
102		HALL	—			HC		14:13	324	
103		FOYER	—			FC		14:14	209	
104		FOYER	—			FC		14:15	267	
105		OFFICE	—			OC		14:17	287	
106		OFFICE	—			OC		14:18	300	
107		LIVING ROOM	—			LRC		14:22	353	
108			—			LRC		14:23	254	
109			—			LRC		14:25	313	
110			—			LRC		14:26	—	INVALID
111			—			LRC		14:30	222	
112		KITCHEN	—			KC		14:35	297	
113		DUPLICATE 112	—			KC		14:36	262	
114		KITCHEN	—			KC		14:38	323	
115		LAUNDRY ROOM	—			LRC		14:41	278	
116		GUEST BATHROOM	—			GBATHC		14:44	291	
117		GUEST BEDROOM	—			GBEDC		14:45	252	
118								14:46	248	DUPLICATE 117
119			—					14:47	263	~~DUPLICATE 118~~ THM

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

VISUAL CORROSION INSPECTION FIELD DATA

Page 1 of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 7/29/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): MAF/TMM WBC

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
		AHU - COIL		INSTALLED 6/06	1	COIL HAS BEEN PAINTED BY OWNER/
						NAVEL JELLY TO REMOVE RUST
						SEEMS NORMAL
		WATER HEATER - GARAGE		LINES	0	NORMAL 0
		WATER HEATER END			0-1	0-1 (NORMAL)
		KITCHEN SINK LINES			0-1	NORMAL
		MASTER BATH SINK LINES			1+	NORMAL (WHITE
						STUFF IS SEALER)
						SOME GREENISH
						FROM SEEPAGE ?
		2nd BATH SINK LINES			1+	SAME AS ABOVE
		FOYER OUTLET	E		0	LOOKS NEW
		FOYER OUTLET	SW		1	NORMAL
		KITCHEN/DR OUTLET	S		1	NORMAL PK BROWN
		MASTER BATH	W	OUTLET	1	NORMAL
		MASTER BR	E	OUTLET	1	NORMAL
		OFFICE	N	OUTLET	1	NORMAL
		BR 2	N	OUTLET	1	NORMAL
		DINING RM	E	OUTLET	1	NORMAL
		GARAGE	N	OUTLET	1	NORMAL
		REFRIGERATOR		LINES	0-1	NORMAL

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

~~VISUAL~~ BULK CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 7/29/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMH, MKF, WEC

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION MKF #	CORROSION RATING	NOTES
99502	1	FOYER	E	7		
99503		OFFICE	S	15		
99504		OFFICE	N	17		
99505		KITCHEN	E	27		
99506		DUPLICATE 99505	E	27		
99507		LIVING ROOM	E	34		
99508		LIVING ROOM	N	36		
99509		GARAGE	S	50		
99510		GUEST BED	N	55		
99511		MASTER HALL	S	69		
99512		MASTER BED	N	86		

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

(b)(6)

HOUSE #2

WIRE TIES

LADDER

House #2 Q trak calibration

QT 12 reads 970 / 1000 span
QT 11 940 / 1000 span
QT 13 1045 / 1000 span
} pre-cal

Recal QT-11 zero reads 0
span reads 1010

QT-11 — LR
QT-12 — master BR
QT-13 — BR 2 = Guest bed rm.

HOBOS LR - S/N 2375369
Master BR 2375364
BR-2 2375368

9:13 → 12:33 200

mm c # 34/k 20 mini

13 20/3 3

072909FL01

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Home Address: (b)(6)

Field Person(s): TAM

Date: 8/20/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
102126		LIVING ROOM	ALDEHYDES	S	8/20/09	930	9/3/09	845	
102127		DUPLICATE		D					
102128		OUTDOORS		S					
102129		GUEST							
102130		MASTER							
102131				FB					
102132				MB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

072909FL01

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: DSC

Date: 8/20/09

Home Address: (b)(6)

Project#: 16,512

Field Person(s): TMM

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
102133		LIVING ROOM	SO_2 NO_2 HF	S	8/20/09	930	9/3/09	845	
102134		DUPLICATE		D					
102135		OUTDOORS		S					
102136		GUEST							
102137		MASTER							
102138				FB					
~~102139~~				MB					NOT ENOUGH MEDIA

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

072909FL01

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/20/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMM

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
102140		LIVING ROOM	H_2S	S	8/20/09	9:30	9/3/09	8:45	
102141		DUPLICATE	↓	D	↓	↓	↓	↓	
102142		OUTDOORS	↓	S	↓	↓	↓	↓	
102143		GUEST	↓	↓	↓	↓	↓	↓	
102144		MASTER	↓	↓	↓	↓	↓	↓	
102145				FB					
102146				MB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

072909FL01

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/20/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
102147		LIVING ROOM	OZONE	S	8/20/09	930	9/3/09	9/3/09	
102148		DUPLICATE		D					
102149		OUTDOORS		S					
102150		GUEST							
102151		MASTER							
102152				FB					
102153				MB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Date: 7/29/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMH, MAF, WEL

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
99524	1	LIVING ROOM	COTTON	S	7/29/09	1547	8/20		
99525		DUPLICATE 99524		D		1547			
99526		OUTDOORS		S		1548			
99527		GUEST ROOM		S		1550			
99528		MASTER BED		S		1551			
99529			BLANK						
99530	1	SUPPLY	COTTON	S	7/29/09	1552			

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

072909FL01

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CDSC

Date: 8/20/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMM

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
102154		LIVING ROOM	COTPAH	S	8/20/09	930	9/3/09	845	
102155		DUPLICATE		D					
102156		OUTDOORS		S					
102157		SUPPLY							
102158		MASTER							
				~~FB~~	TMM				

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 7/29/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): WBC/MAF/TMM

Camera ID: ECAMP 22

PHOTO NO.	FLOOR	LOCATION	NOTES
100-0001-0003		LIVING/DINING Room	
04-05		KITCHEN	
06-07		OFFICE	
08-10		FOYER	
11		BATH 2	
12-13		BEAROOM 2	
14-15		LAUNDRY	
16-20		MASTER SUITE	
21-29		AHU-COIL	NORMAL? CORROSION
30		WATER HEATER LINES	NORMAL GN WIRE
31		WATER HEATER GND	NORMAL
32		KITCHEN SINK LINES	NORMAL
33-38		MASTER BATH SINK LINES	NORMAL E1
39		SECOND BATH SINK LINE	NORMAL
40		OUTLET ?2	NORMAL
41		DINING RM OUTLET	NORMAL
42-44		REFRIGERATOR LINES	NORMAL
45		MASTER CLOSET BULK SAMPLE COVER	