080609 FC02

ENVIRONMENTAL HEALTH & ENGINEERING

Environmental Health & Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

House ID _____

Date 8/6/09

Field Technician(s) (b)(6)

House Address _____

General Weather Description SUN / HOT / HUMID

1. Questionnaire

1) Interviewed home owner (YES) NO

2) Age of the House (years) 2006 built
occ. Sept 2006

3) Estimated Floor Area (sqft) 3BR 2bath singlestory ranch
2100 sf

4) Was ~~as~~ there any demo's to the house?

YES (NO)

If YES, when was it done? Please Explain.

_____

5) Has there been any fire in the building?

YES (NO)

If YES, when did it happen? Please Explain.

_____

6) Any pesticides/herbicides been applied around the building or in the yard?

(YES) NO

If YES, when was it applied? Please list the type of chemicals used.

roundup, ~~[illegible]~~ bugkiller

7) Has there been any recent painting/staining done in the home?

YES NO

If YES, when, where and what type of paint/stain was used?

_____.

8) Has any work been done on the AC system since construction?

YES NO

If YES, please describe?

_____.

9) Are all the AC system components original?

YES NO

If NO, please describe?

_____.

10) What is the age of your refrigerator? 2006 (since constr.) (purchased/ordered when bought house)

_____ years

11) Has any piping been replaced in the home?

YES NO

If YES, please describe?

_____.

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many units?

_____.

2) Number of rooms

_____.

3) Above grade Construction

Wood Frame Concrete & metal Stone Brick Other _____

see Pictures 10/15/09 WSW

attic crawlspace access via garage & bathroom

4) Basement

Full Crawlspace Slab Other _____

5) Foundation

Concrete Cinder Block Stone Other_____

6) Garage

YES NO

If YES, Attached Detached

If YES, Used for Car Parking? YES NO

If YES, Any gas-powered equipment or cans of gasoline/fuels stored? YES NO gas for leaf blower

7) Type of HVAC System

5-TON DX COOLING / GAS FURNACE

(b)(3):CPSA Section 6(b)

M HVAC Model CNRVPL024ATAAAAA Condenser Model 24ABA360A300

8) Types of Fuel (circle all that apply) stove, water heater, bbq grill, furnace, clothes dryer

Natural Gas Fuel Oil Kerosene Electric

Propane Solar Wood Coal

9) Water Supply

Public Well Other _____

10) Sewage

Public Septic Leach Field Other _____

11) Attic

Finished Unfinished

3. Interior Characteristics

1) Any odors upon entering the building?

YES NO

If YES, describe _____

2) Fireplace

YES NO

3) Floors (circle all that apply)

w/ some throw-rugs-carpets on top

Hardwood Carpet Ceramic Tile Vinyl Tile

Unfinished Wood Unfinished Concrete Other _____

4) Walls (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

5) Ceiling (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

House Address (b)(6)

Page 1/2



House Address (b)(6)

Page 2/2



VOC SAMP FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

SUMMA

Client: CPSC

Date: 8/6/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): _____

SAMPLE ID	CANISTER ID	FLOW CONTROL ID	GAUGE ID	FLOOR	LOCATION	SAMPLE TYPE	GAUGE PRESSURE START	START TIME	GUAGE PRESSURE END	END TIME	NOTES
100214	AC00972	FC00418		1	LIVING RM	S		10:16	9"	12:23	
100215	AC01236	FC00479			DUP of LR	D		10:16	8"	12:23	
100216	AC01670	FC00503			OUTDOOR	S		10:17	7"	12:25	
100217	AC00407	FC00611			GUEST	S		10:17	10"	12:26	
100218	AC00215	FC00506			MASTER	S		10:17	6"	12:24	
100219	AC00518	FC00310			Blank	FB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM. Ξ FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MHR WEC MED

day 4

C of CFx

Date: 8/6/09
Project#: 16512
ROTA ID #: EGLTR08

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100222	1	Living Rm	ORGANICS	S	13858	.507	10:14	.513		202	103 L
100220	1	Dup of LR		D	10483	.498		.469		204	98.6
100230	1	OUTDOORS		S	13481	.503		.480		205	100.8
100055	1	GUEST BR		S	06259	.504		.492		207	103.1
100228	1	MASTER BR		S	02994	.498		.512		200	101
100058	—	Field Blank		FB	—	—	—				OL

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM Ξ FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

~~SUMMY~~

day 4

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC/MHK/MD

Date: 8/6/09

Project#: 16512

ROTA ID #: EGLTR08

C of C F ✓

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100221	1	Living Rm	INORGANIC	S	12989	.525	10:14	.527		204	107.3L
100226	1	Dup of LR	↓	D	12501	.506	↓	.499		202	101.6
100229	1	OUTDOOR	↓	S	02711	.504	↓	.462		206	99.5
100056	1	GUEST BR	10486	S	~~06759~~	.502	↓	.485		207	102.2
100227	1	MASTER BR	↓	S	13459	.509	↓	.497		203	102.1
100057	—	Field Blank		FB	—	—	—				0L

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Page __ f ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MAK MED WEC

Date: 8/6/09

Project#: 16512

ROTA ID #: EGLTR08

CofCFU

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100080	1	LIVING RM	ALDEHYDE	S	02816	.518	10:14	.523		202	105.0L
100081	1	Dup of LR		D	07766	.501		.512		201	101.7
100223	1	OUTDOORS		S	10142	.508		.494		205	102.7
100224	1	GUEST BR		S	13445	.503		.490		206	102.3
100082	1	MASTER BR	✓	S	06737	.510		.507		[redacted] 201	102.2
100225	—	Field Blank		FB	—	—	—				0

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

GRAB SAMPLES

Client: CPSC

Date: 8/6/09

Project#: 16512

Home Address (b)(6)

ROTA ID #:

Field Person(s): WEC/MHK/MD

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100290		LIVING ROOM					17:10			.5	
100291		DUP 100290					17:11				
100292		OUTDOORS					17:15				
100293		MASTER BR					17:17				
100294		GUEST BR					17:20				

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

HOUSEID: 080609FL02

XRF SCAN FIELD DATA

Page 1 of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address (b)(6) [redacted]

Field Person(s): _____

Date: 8/6/09
Project#: 16512

XRF Serial #: 10452
XRF Scan Time: 30 sec

1 = stdz, 7

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
2	1	Masterbath	W	7' above mirror	textured		SCAN		10^{21}	686	
3		" "	W	4' just above tub					10^{22}	512	
4		" "	N	4' " " "					10^{23}	308	
5		" "	E	2' up to shower					10^{24}	1113	
6		" "	E	7'					10^{25}	298	
8		" "	S	7' above door					10^{31}	975	
9		" "	S	4' switch					10^{32}	337	
10		Water closet/toilet	N	2' left of toilet					10^{34}	455	
11			N	7' above cabinet					10^{34}	420	
12			W	4' switch					10^{35}	758	
13			W	4' switch					10^{35}	758	Dup of 12
14			W	7' above door					10^{36}	423	
15			S	2'					10^{37}	393	
16			S	7'					10^{38}	1019	
17			E	3'					10^{38}	401	
18			E	7'					10^{39}	414	
19		Closet 1 (masterbath hallway)	N	2'					10^{40}	928	
20			N	7'					10^{40}	1141	
21			N	7'					10^{41}	876	Dup of 20

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/6/09

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
22	1	Closet #1	W	2'	texture		SCAN		1042	704	
23			W	7' above door					1042	1381	
24			S	2'					1042	701	
25			S	7'					1042	613	
26			E	2'					1045	994	
27			E	7'					1046	593	
28		Hall to master bath	E	4' switch					1047	453	
29		" "	E	7' above closet door					1047	892	
30		" "	W	18" outlet					1048	896	
31		" "	W	18" outlet					1049	970	Dup of 30
32		" "	W	7' above closet door					1049	822	
33		Closet #3	E	2'					1050	1204	
34		" "	E	7'					1051	1055	
35		" "	N	2'					1051	937	
36		" "	N	7'					1052	984	
37		" "	W	7'					1053	929	
38		" "	W	2'					1054	786	
39		" "	S	2'					1054	692	
40		" "	S	7					1055	756	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/6/09

Project#: 16572

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
41	1	Closet #3	S	7'	Textured		SCAN		10:54	708	Dup of 40
42		(Closet #2	N	4'					10:57	1125	
43		(linen closet)	S	4'					10:58	742	
44			E	2'					10:58	946	
45			E	5'					10:59	603	
46		Master Bed	N	18"	outlet				11:00	558	
47		" "	N	5'	switch				11:01	872	
48			W	2'					11:01	269	
49			W	7'					11:02	917	
50			S	4'	switch				11:02	578	
51			S	4'	switch				11:03	582	Dup of 50
52			S	7'					11:04	309	
53			E	18"	outlet				11:05	977	
54			E	7'	(adj to high wall-mounted tv) outlet				11:06	490	
55		Hall/Alcove from MBR	W	3'					11:30	430	
56		" " "	W	6'					11:30	416	
57		" "	N	18"	outlet				11:31	803	
58		" "	N	7'					11:31	1008	
59		Living Rm	W	18"	outlet				11:32	635	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page 4 of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/6/09

Project#: 16572

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
60	1	Living Rm	W	7'	Textured		SCAN		11:33	591	
61			W	7'					11:34	647	Dup of 60
62			S	2'					11:34	645	
* 63			S	5' knob/dimmer switch					11:35	1134	
64		FOYER/ENTRY	W	7' above closet door					11:36	589	
65		inside entry closet ~~[illegible]~~	N	7'					11:36	800	
66		inside entry/Foyer closet	S	2'					11:38	663	
67		" " "	W	2'					11:39	574	
68		" " "	W	7'					11:39	778	
* 69		FOYER	N	4' switch					11:40	343	
70		Foyer half-wall	E	2'					11:40	826	
71		" " "	E	2'					11:41	851	Dup of 70
* 72		" " "	W	18" outlet					11:42	779	
73		Dining Rm	W	7'					11:43	689	
74			N	2'					11:44	570	
75			N	7'					11:44	557	
76			E	7'					11:45	800	
* 77			E	4' switch					11:45	496	
78			S	2'					11:46	941	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/6/09

Project#: 16572

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
79	1	Dining Rm	S	7'	Texture		SCAN		11:47	697	
(*) 80		Living Rm	E	18" outlet					11:48	797	
81			E	18" outlet					11:48	930	Dup of 80
82			E	7' above entry to kitchen					11:49	570	
83		Laundry RM	W	7'					11:50	799	
(*) 84			W	4' switch					11:51	456	
85			W	2'					11:51	503	
86			W	7'					11:52	533	
87			S	2'					11:53	875	
88			S	7'					11:53	660	
89			E	2'					11:54	635	
90			E	4'					11:55	1166	
91			E	4'					11:55	1154	Dup of 91
(*) 92		main hallway	N	4' switch					11:56	1238	
93		" "	N	7'					11:57	869	
94		Kitchen	NW	4'					11:58	1149	
95				7'					11:59	433	
(*) 96				4' switch					12:00	1078	
97		PANTRY interior	S	4'					12:06	1387	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page 6 of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/6/09

Project#: 16572

XRF Serial #: _____

XRF Scan Time _____

Std z = 113,114

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
98	1	Pantry	N	4'	Texture		SCAN		1206	1204	
99			N	6'					1207	731	
100			N	2'					1208	504	
101			N	2'					1208	489	
102			W	4'					1209	302	
103			W	2'					1210	325	
104		KITCHEN	E	2'					1211	902	
105			E	7'					1211	1013	
106			S	18" outlet					1212	585	
107			S	7' above clock					1213	509	
108			W	7'					1213	893	
109			W	4' switch					1214	733	
110		" on half wall	S	2'					1215	931	
111		" " "	S	2'					1216	853	Dup of 110
112		main hall	E	18" outlet					1218	ND	
115		" "	E	18" outlet					1221	660	
116			E	7' above painting					1222	681	
117			E	4' switch					1222	737	
118			W	2'					1223	432	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/6/09

Project#: 16512

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
119	1	Main hallway	W	7'	Texture		Scan		12:24	1159	
120		OFFICE	~~E~~ S	18" outlet					12:26	841	
121		"	~~E~~ S	" "					12:26	752	Dup of 120
122		"	S	7'					12:27	582	
123		"	W	4' switch					12:28	837	
124		"	W	7'					12:29	870	
125		"	N	2'					12:29	500	
126		"	N	7'					12:30	762	
127		"	E	7'					12:31	873	
128		"	E	18" outlet					12:31	669	
129		inside office & Closet	W	4'					12:32	871	
130		" "	E	4'					12:33	742	
131		" "	E	4'					12:34	709	Dup of 130
132		" "	S	6'					12:34	903	
133		" "	S	4'					12:35	748	
134		Bathroom	W	4' switch					12:36	784	
135			W	7' above door					12:37	816	
136			N	8' above tiled shower					12:37	617	
137			N	2' by toilet					12:38	705	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/6/09

Project#: 16512

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
138	1	Bathroom	W	4' switch	Texture		SCAN		1239	(66)	
139		(toilet alcove)	W	7'					1240	1056	
140			E	7'					1240	322	
141			E	7'					1242	297	Dup of 140
142			E	2'					1242	282	
143		linen closet	E	4'					1243	586	
144			W	4'					1244	452	
145			S	4'					1245	533	
146		Bathroom above mirror	S	7'					1245	567	
147		BR2 closet	W	4'					1247	563	
148		" "	E	4'					1248	1209	
149		" "	N	5'					1248	1336	
150		BR2	N	18" outlet					1250	402	
151		BR2	N	"					1251	428	Dup of 151
152			N	7'					1252	938	
153		BR2 Guest BR	E	18" outlet					1253	425	
154			E	7'					1253	851	
155			S	2'					1254	873	
156			S	7'					1255	872	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page 9 of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/6/09

Project#: 16512

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
157	1	BR2 (Guest BR)	W	2'	Texture		SCAN		12:55	751	
158		↓	W	7'					12:56	567	
159		GARAGE	W	6'					12:57	845	
(*) 160		"	S	4' switch					12:58	434	
161		"	S	4' "					12:59	388	Dup of 160
(*) 162		"	S	4' socket/outlet by water heater					1:00	409	
C163		"	—	ceiling					1:02	1171	
C164		"	—	ceiling					1:03	338	
C165		Laundry Rm	—	ceiling					1:09	329	
C166		Kitchen		ceiling					1:16	423	
C167		Kitchen "eating area"		ceiling					1:17	344	
C168		Living Rm		ceiling					1:19	303	
C169		Dining Rm		ceiling					1:20	349	
C170		~~BR3~~ Guest BR							1:22	412	
C171		Guest BR							1:23	408	Dup of 170
C172		Guest Bath							1:24	436	
C173		office							1:26	481	
C174		main hall							1:28	304	
C175		Master Bath							1:29	250	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSL

Home Address: (b)(6)

Field Person(s): _____

Date: 8/6/09

Project#: 16572

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
C176	1	master closet 1	—	ceiling	Texture		SCAN		145	990	
C177		master closet 3	—	ceiling					147	885	
C178		HALL of Master Bed Rm	—	Ceiling					148	873	
C179		Master Bed Rm	—	ceiling					150	418	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

VISUAL CORROSION INSPECTION FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/6/09

Home Address: (b)(6)

Project#: 16512

Field Person(s):

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
	1	GARAGE - AHU COIL			2+	
	1	GARAGE - WATER HEATER			0	CUPLATED FLEX LINES
	1	GARAGE	S	SWITCH	2	
	1	KITCHEN FAUCET LINES			2	
	1	REFRIGERATOR LINES / EXP. TUBE			2+	
	1	MASTER BATH FAUCET LINES			0-1	
	1	MASTER BATH DOOR STOP			1-2	CHROME ?
		GUEST BATH FAUCET			0	LOOKS NEW
		GUEST BATH TOILET SHUTOFF			0	LOOKS NEW
		MASTER BATH SWITCH		# 9	2	
		MASTER BR OUTLET		# 54	2	
		MASTER BR SW		# 28	2	
		MASTER BR OUTLET		# 46	2	
		HALL OUTLET		# 57	2	
		LR OUTLET		# 59	2	
		LR OUTLET		# 63	2	
		DR DIMMER SW.		# 77	2	
		LR OUTLET		# 80	2	
		HALL SW.		# 92	2	
		KITCHEN SW.		# 96	2	
		FOYER SW.		# 69	2	
		LAUNDRY SW.		#84	2	
		KITCHEN OUTLET		#106	2	
		BR 1		# 120	2	
		BR 2		# 150	2	
		BR 2		# 153	2	

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

~~VISUAL CORROSION~~ INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

BULK

Client: CPSC

Date: 8/6/09

Home Address: (b)(6)

Project#: 16512

Field Person(s):

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	~~CORROSION RATING~~	NOTES
100273	1	Master bath	S	9 Switch		
~~—~~	~~1~~	~~Master bath/WC~~	~~W~~	~~12 Switch~~	~~MED~~	
100260	1	Hall to master bath	E	28 Switch		
100272		Master BR	N	46 outlet		
~~—~~		~~" "~~	~~N~~	~~47 Switch~~		~~MED~~
~~—~~		~~" "~~	~~S~~	~~50 Switch~~		~~MED~~
100270		" "	E	54 high outlet by tv		
100265		Hall/alcove from master BR	N	57 outlet		
100261		Living RM	W	59 outlet		
100269		" "	S	63 dimmer switch		
100278		Foyer	N	69 Switch		
100131		Dining RM	E	77 Switch		
100268		Living RM	E	80 outlet		
100267		Laundry RM	N	84 switch		
100276		Main Hallway	N	92 switch		
100263		Kitchen	NW	96 switch		
100271		"	S	106 outlet		D 100266
100121		Office	S	120 "		
100283		Guest BR	N	150 outlet		
100258		" "	E	153 outlet		
100264		Garage	S	160 switch		D 100284

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

(b)(6) [redacted]

8/6/09 Sun City

LR HOBO #2412451
LR QT 22

~~BR2~~ guest BR HOBO 2412435
QT 25

8/7/09

(b)(6) [redacted] NORTH PORT

LR HOBO 2412452
QT-22

master BR 2412446 HOBO
QT-29

ID: 080 9FL02

PASSIVE SAM .E FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/6

Home Address: (b)(6)

Project#: 16512

Field Person(s): [illegible]

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100231	1	LR	H_2S	S	8/6/09	15:28	8/20/09	8:00	
100232		LR dup		D					
100233		Outdoor		S					
100234		Master BR		S					
100235		Guest BR		S					
100236		Media Blank		MB		—			
100237		LR	O_3	S		15:41			19
100238		LR Dup		D					
100239		Outdoor		S					
100240		Master BR		S					
100241		Guest BR		S					
100242		MB		MB		—			
100243		LR	NO_2, SO_2, HF	S		15:52			8
100244		LR dup		D					
100245		Outdoor		S					
100246		Master BR		S					
100247		Guest BR		S					
100248		MB		MB		—			
100249		LR	Aldehydes	S		15:56			4

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ID: 080609FL02

PASSIVE SAM _E FIELD DATA

Page __ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address (b)(6)

Field Person(s): MIK MED UEL

Date: 8/6/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100250	1	LR dup	Aldehydes	D	8/6/09	15:56	8/6/09	800	
100251	↓	Outdoor	↓	S	↓	↓	↓	↓	
100252	↓	Master BR	↓	S	↓	↓	↓	↓	
100253	↓	Guest BR	↓	S	↓	↓	↓	↓	
100254	↓	MB	↓	MB	↓	—	—	—	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ID: 080'29FL02

PASSIVE SAM _E FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/6/09 MED

Home Address: (b)(6)

Project#: 16512

Field Person(s): MAR WEC MED

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100255	1	LR	Capon	S	8/6/09	16:05	8/20/09	8:00	15 55
100256	↓	HVAC Diffuser	↓	S	↓	↓	↓	↓	
100286	↓	Outdoor	↓	S	↓	↓	↓	↓	
100287	↓	Master BR	↓	S	↓	↓	↓	↓	
100288	↓	Guest BR	↓	S	↓	↓	↓	↓	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/6/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): WEC/MHK/MD

Camera ID: ECAMP 22

PHOTO NO.	FLOOR	LOCATION	NOTES
1-5		EXTERIOR	
6-10		CONDENSER - (b)(3):CPSA Section 6(b) F 24ABA 360A 300	
11		GAS METER	
12-16		LR ~~R~~/DR AREAS	
17-21		KITCHEN	
17		LAUNDRY	
~~18~~	~~4~~		
22-27		GARAGE	CINDER BLOCK WALLS - 3 SIDES
28-31		BR 1 - GUEST NE	
32		HALL	
33-34		GUEST BATH	
35-37		BR 2 - GUEST - SE	
38-45		MASTER BATH/BR	
46		AHU TAG - (b)(3):CPSA Section 6(b) CNRVP602HAT AAAAA	DX COOLING GAS HEAT 5-TON
47-51		AHU - COIL	
52		~~KITCHEN FAUCET LINES~~ WATER HEATER LINES	
53/54		GARAGE SWITCH S	
55		KITCHEN SINK FAUCET LINES	
56/57		REFRIGERATOR LINES	
58/59		MASTER BATH FAUCET LINES	
60		MASTER BATH DOOR STOP	
61		GUEST BATH FAUCET	
62		GUEST BATH TOILET SHUT OFF	
63		MASTER BATH SWITCH #9	
64		MASTER BR OUTLET-TV #28	
65		MASTER BR OUTLET #46	
66		LR OUTLET #63	
67		KITCHEN SW. #96	

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/6/09

Home Address: (b)(6)

Project#: 16572

Field Person(s): WEC/MHK/MD

Camera ID: ECAMP 22

PHOTO NO.	FLOOR	LOCATION	NOTES
68		BR 1 # ~~[illegible]~~ 120	