080709 FL02

ENVIRONMENTAL HEALTH & ENGINEERING

Environmental Health & Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

House ID _____

Date 8/7/09

Field Technician(s) MED MHK WEC

House Address (b)(6) North Port

General Weather Description hot/overcast

1. Questionnaire

1) Interviewed home owner YES NO

2) Age of the House (years) finished Jan. 07 (built 2006)
occup. by owner Jul '08 – unocc. previous to that

3) Estimated Floor Area (sqft)
1684 3BR 2Bath 1 story ranch

4) Was ~~as~~ there any demo's to the house?

YES NO

If YES, when was it done? Please Explain.
* Builder came in & remove/replace entire 2 sections of wallboard. 1 in living rm, 1 in master bedrm (both on west wall)

5) Has there been any fire in the building?

YES NO

If YES, when did it happen? Please Explain.
1. @ machinery assoc w/ well (fire, melted mech/pump unit)
(after) 2. smoke but no flames in utility rm.

6) Any pesticides/herbicides been applied around the building or in the yard?

YES NO

If YES, when was it applied? Please list the type of chemicals used.
just roundup & raid type products

7) Has there been any recent painting/staining done in the home?

YES NO

If YES, when, where and what type of paint/stain was used? latex paint kitchen & family RM mastorbath

8) Has any work been done on the AC system since construction?

YES NO

If YES, please describe?

replacement Feb '09 of coils ; stopped working in Nov 08

9) Are all the AC system components original?

YES NO

If NO, please describe?

replaced coils ;

10) What is the age of your refrigerator? 2008

_____ years

11) Has any piping been replaced in the home?

YES NO

If YES, please describe?

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many units?

Single Story ranch

2) Number of rooms

3) Above grade Construction

Wood Frame Concrete Stone Brick Other _____

4) Basement

Full Crawlspace Slab Other _____

5) Foundation

Concrete Cinder Block Stone Other_____

6) Garage

YES NO

If YES, Attached Detached

If YES, Used for Car Parking? YES NO

If YES, Any gas-powered equipment or cans of gasoline/fuels stored?

YES NO habitually/ in past but not currently

7) Type of HVAC System

DX COOLING, ELECT. RESISTIVE HEATER ELEMENT IN AHU

(b)(3):CPSA Section 6(b)

VAC Model ARUF36A216AA Condenser Model 6SH130361A A

8) Types of Fuel (circle all that apply)

Natural Gas Fuel Oil Kerosene Electric ALL

Propane Solar Wood Coal

9) Water Supply

Public Well Other _____

10) Sewage

Public Septic Leach Field Other _____

11) Attic

Finished Unfinished /crawlspace only

3. Interior Characteristics

1) Any odors upon entering the building?

YES NO

If YES, describe Sulfur

2) Fireplace

YES NO

3) Floors (circle all that apply)

Kitchen & bath only

Hardwood Carpet Ceramic Tile Vinyl Tile

Unfinished Wood Unfinished Concrete Other _____

4) Walls (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

5) Ceiling (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

(b)(6) [redacted]

House Address

Page 1/2

House Addre (b)(6)

Page 2/2

NORTH PORT

• = loc of GUEST room sampling



ACTIVE SAM E FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

day 5

Date: 8/7/09

Project#: 16512

Home Address: (b)(6)

ROTA ID #: E6LTR08 (EH&E)

Field Person(s): MED MHK WEC

C of CF +

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100320	1	LIVINGRM	INORGANICS	S	13501	.497	8:23	.496		211	104.5
100321	1	Dup of LR		D	12989	.506	8:23	.510		211	107.2
100329		OUT DOOR		S	13009	.499	8:22	.483		217	106.5
100325	1	MASTER BR		S	13459	.496	8:23	.478		215	104.7
100322	1	GUEST BR		S	13481	.507	8:23	.490		213	106.2
100324		BLANK									OL

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Page __ f ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

day 5

Date: 8/7/09
Project#: 16512

Home Address: (b)(6)

ROTA ID #: EHEEG4TR08 (EH&E)

Field Person(s): MED MHK WEC

C of C Fr

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100323	1	LIVING RM	ORGANICS	S	13858	.516	8:23	.516		211	108.9 L
100319	1	Dup of LR		D	07766	.505	8:23	.516		211	107.6
100326		OUTDOOR		S	06737	.505	8:23	.473		217	106.1
100330	1	MASTER BR		S	06759	.501	8:23	.489		214	105.9
100327	1	GUEST BR		S	10142	.499	8:23	.480		214	104.9
100328		BLANK		MB							OL

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MED MHK WEC

Date: 8/7/09

Project#: 16512

ROTA ID #: EGROTR08

C of CF ✓

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100311	1	LIVING RM	ALDEHYDE	S	02816	.490	8:23	.495		211	103.9
100310	1	Dup of LR	|	D	10483	.505	8:23	.505		210	106.1
100314		OUTDOOR	|	S	10486	.503	8:22	.394		216	96.9
100318	1	MASTER BR	|	S	02991	.500	8:23	.514		215	109
100317	1	GUEST BR	|	S	02711	.506	8:23	.494		213	106.5
100304		BLANK	✓	MB							0

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

GRAB

Client: CPSC

Home Address: (b)(6)

Field Person(s): MED/MHK/WEC

C of C Fu

Date: 8/7/09

Project#: 16512

ROTA ID #:

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100365	1	LIVING RM	SULFUR	AIR	17425		13:19			.5	30 sec Grab
~~100366~~	~~1~~	~~Dup of LR~~					~~13:20~~				
	1	OUT DOORS									
100366	1	MASTER BR					13:20				
100367	1	GUEST BR					13:22				
100368	1	Dup of LR	Sulfur	Air	13425		13:24				

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

HOUSEID: 080709FL02

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s):

Date: 8/7/09
Project#: 16572

XRF Serial #: 10452
XRF Scan Time 20

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
* 2	1	Living Rm	N	4' switch	Textured		SCAN		8:38	228	
3			N	7					8:39	1204	
* 4			E	18" outlet					8:40	~~1388~~	mod 1380
5			E	7'					8:41	1489	
6			S	7'					8:42	1451	
* 7			S	4' light switch					8:42	393	
* 8			S	18" outlet					8:43	1174	
9			S	7'					8:44	447	
10			W	7'					8:44	1048	original wallboard
11			W	7'					8:45	1195	Dup of 10
12			W	5'					8:46	1492	~~[illegible]~~ original wallboard
13			W	2'					8:46	181	Replacement wallboard - "National Gypsum" label
14			W	2'					8:47	183	" "
15			N	7'					8:48	432	
* 16			N	4' switch					8:49	448	
17		Corner shelf inset	W	4' @shelf inset					8:50	990	
18		HALL	W	7'					8:51	1159	
19			W	2'					8:51	1388	
* 20			E	18" outlet					8:52	659	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s):

Date: 8/7/09

Project#: 16512

XRF Serial #:

XRF Scan Time

	SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
*	21	1	HALL	E	18" outlet	Texture		SCAN		8:53	735	Dup of #20
	22		↓	E	7'					8:53	543	
	23		HALL Closet	N	4'					8:53	250	
	24			S	4'					8:55	298	
	25			E	7'					8:56	270	
	26			E	2'					8:57	268	
	27		PANTRY	E	4'					8:59	375	
	28			W	4'					8:59	329	
	29			S	7'					9:00	447	
*	30		Kitchen	E	4' outlet					9:01	291	
	31			E	4'					9:02	280	Dup of 30
	32			E	6' next to fridge behind fridge					9:03	1480	
	33			S	6'					9:03	795	
*	34			W	4' outlet					9:04	636	
	35			W	7'					9:05	400	
	36		" outside pantry	E	7'					9:06	1355	
*	37		Utility Rm	E	4' switch					9:06	510	
	38			E	7'					9:07	1107	
	39			N	2'					9:08	1180	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s):

Date: 8/7/09

Project#: 16512

XRF Serial #:

XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
40	1	Utility Rm	N	7'	Texture		SCAN		908	1280	
41			N	7'					909	1237	Dup of 40
42			W	2'					910	1678	
43			W	7'					911	1124	
(*) 44		Family Rm side of (outer) of Kitchen ½ wall	NE	18" outlet					912	404	
45		" " " "	N	18"					912	905	
46		Master Bath	N	2' next to toilet					917	1192	
(*) 47			N	4' switch					918	659	
48			E	7' above mirror					918	1098	
49			E	4' above tub					920	1185	
50			S	4' " "					921	791	
51			S	4'					921	795	Dup of 50
52			S	7'					922	1098	
53			W	5' btw n tub and shower					923	1430	
54			S	7' above shower					924	1144	
55			W	7' above shower					924	1309	
56			W	2' by toilet					925	1033	
57		Master Closet	N	4'					928	412	
58		" "	E	4'					929	647	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/7/09

Project#: 16572

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
59	1	Master Closet	S	7'	Texture		SCAN		929	781	
60			E	2'					930	1265	
61			E	2'					931	1020	Dup of 60
62			E	7'					931	1050	
63			S	2'					932	781	
64			S	7'					933	992	
65			W	7'					933	1033	
66			W	2'					934	750	
67		Master BR	E	4' switch					935	226	
68			E	7'					936	1223	
69			N	18" outlet					937	365	
70			N	7'					938	1249	
71			N	7'					938	1207	Dup of 70
72			W	5'					939	950	original wallboard
73			W	7'					939	932	" "
74			W	3'					940	174	replacement wallboard
75			W	3'					941	183	labelled "National Gypsum"
76			S	7'					941	1185	
77			S	18" outlet					942	361	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): 95=Std z

Date: 8/7/09
Project#: 16512

XRF Serial #:
XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
78	1	Family Rm	S	4'	Texture		SCAN		943	326	
79			W	7'					944	1468	
* 80			W	18" outlet					944	958	
81			W	18" outlet					945	976	Dup of 80
82			N	7'					946	1380	
* 83			N	4' switch					947	337	
84			E	7'					948	1713	
85		(inser wall	N	2'					948	777	
* 86		(inser wall	E	18" outlet					949	909	
87		(inser wall	E	7'					949	888	
88			E	4'					950	401	
89			S	4'					950	1503	
90		Closet #1	W	3'					952	337	
91			W	3'					953	384	Dup of 90
92			N	5'					955	402	
93			E	2'					956	1384	
* 95		Hallway to Guest BRs	S	4' switch					1002	169	
96			E	7'					1002	820	
97		GUEST BR1 Closet	S	2'					1004	1372	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s):

Date: 8/7/09

Project#: 16572

XRF Serial #:

XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
98	1	Guest BR1 /Closet	E	7'	Texture		SCAN		10:05	510	
99			E	2'					10:05	1320	
100			N	7'					10:06	884	
101			N	7'					10:07	864	Dup of 100
102			W	2'					10:08	1142	
103			W	7'					10:09	936	
* 104		Guest BR1	S	18" outlet					10:10	606	
105			S	7'					10:10	1327	
106			E	7'					10:11	485	
* 107			E	18" outlet					10:12	1423	
108			N	7'					10:13	1227	
* 109			N	4' switch					10:13	240	
110			W	7'					10:14	1405	
111			W	7'					10:15	936	Dup of 110
112			W	3'					10:15	807	
113		Bath (Guests)	W	7'					10:16	1009	
* 114			W	4' switch					10:16	183	
115			S	2'					10:18	391	
116			S	7' above shower					10:18	1144	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s):

Date: 8/7/09

Project#: 16512

XRF Serial #:

XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
117	1	Guests' Bath	E	7' above shower	Texture		SCAN		10:19	241	
118			N	7' above shower					10:20	1387	
119			N	2'					10:20	929	
120		Guest BR2 Closet	N	4'					10:21	394	
121			N	4'					10:22	351	Dup of 120
122			S	4'					10:22	324	
123			W	7'					10:23	1200	original wallboard
124			W	2'					10:24	185	"National Gypsum" replacement wallboard
* 125		GUEST BR2	N	18" outlet					10:25	1025	
126			N	7'					10:25	1410	
* 127			E	18" phone jack					10:26	283	
128			E	7'					10:27	1463	
129			S	7'					10:27	872	
* 130			S	4' switch					10:28	253	
131			S	4'					10:28	250	Dup of 130
132			W	7'					10:29	1417	
* 133			W	18" outlet					10:30	543	
C134		Guest BR1 Closet	—	Ceiling					10:32	313	
C135		Guest BR	—	"					10:32	248	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s):

Date: 8/7/09
Project#: 16512

XRF Serial #:
XRF Scan Time

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
C136	1	GUEST HALLWY	—	Ceiling	Texture		SCAN		1033	300	
C137		Guests' Bath	—	Ceiling					1034	310	
C138		Guest BR2 Closet	—	ceiling					1035	384	
C139		Guest BR2	—	Ceiling					1035	199	
C140		FAMILY RM (inset/ALCOVE)	—	Ceiling					1037	334	
C141		" " "	—	"					1037	298	Dup of 140
C142		FAMILY RM (E)	E	"					1038	231	
C143		" " (W)	W	"					1039	256	
C144		Master BR closet	—	"					1040	1006	
C145		Master BR Bath RM	—	"					1041	1202	
C146		Master BR	—	"					1042	964	
C147		Kitchen 8' wall (on top of wall)	—	on top of 8' wall btwn kitchen & Living Rm that does not connect w/ ceiling					1043	1656	
C148		Living RM W	W	Ceiling					1044	265	
C149		Living RM E	E	Ceiling					1045	353	
150		Garage	E	7'					1049	302	
151			E	5'					1050	268	
152			E	5'					1050	252	Dup of 151
153			E	4'					1051	254	
(*) 154			N	4' switch					1052	349	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/7/09

Project#: 16512

XRF Serial #: _____

XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
* 155	1	Garage	N	6' Home outlet plate	texture		SCAN	S	10:53	342	
C156	1	"	—	Ceiling					10:53	259	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

VISUAL CORROSION INSPECTION FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/7/09

Home Address (b)(6) NORTHPORT

Project#: 16512

Field Person(s): MEC/MHK/MED

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
	1	GARAGE - WATER HEATER			0-1	PLASTIC/BRASS
		AHU COIL/LINES		LAUNDRY ROOM	2+	
		LAUNDRY SHUTOFF VALVE/HAMMER ARRESTER			1-2	BRASS/COPPER
		DRYER OUTLET CONTACTS			1-2	BRASS/COPPER?
		KITCHEN SINK CHROME PLATING			2	
		KITCHEN SINK FAUCET LINES - CU			1	
		REFRIGERATOR LINES/EXP. TUBE			2	
		MASTER BATH SINK LINES			2	
		" " TOILET SHUTOFF			0	NORMAL/DIRTY
		" " SHOWER BEZEL CHROME			0-1	MINOR ETCHING
		" " TUB SPOUT - CHROME			1-2	MAJOR PITTING
		COPPER "COUPON" - MASTER BATH			1-2	
		2nd BATH TUB BEZEL/SPOUT/TOILET			2	MAJOR PITTING/RUST/CORROSION
		2nd BATH SINK LINES			2	
		LR SWITCH.	N	#2	2	
		DR OUTLET	N	#16	2	
		DR OUTLET	S	#8	2	
		LR OUTLET	E	#4	2	
		HALL OUTLET	E	#20	2	
		DEN OUTLET	S	#44	2	
		KITCHEN OUTLET	E	#30	2	
		KITCHEN OUTLET	W	#34	2	
		UTILITY ROOM SW	E	#37	2	
		GARAGE SW.		#154	1	
		~~KITCHEN~~ MASBR SW	E	#67	2	
		MASTER BR OUTLET	N	#69	2	
		M. BATH OUTLET	N	#47	2	
		DEN SW.	N	#83	0-2	VARIES FROM 0-2

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

VISUAL CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date:

Home Address: (b)(6)

Project#: 16512

Field Person(s): MED MHK WEC

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
		6. BR #1 SW	N	# 109	2	
		6. BR #1 OUTLET	S	# 104	2	
		6. BR #2 SW	S	# 130	2	
		6. BR #2 OUTLET	N	# 125	2	

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

VISUAL CORROSION INSPECTION FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

BULK SAMPLES

Client: CPSC

Date: 8/7/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): MED MHK WEC

SAMPLE ID	FLOOR	LOCATION	WALL COOR. N,E,S,W	SAMPLE LOCATION Loc#	CORROSION RATING (outlet/switch?)	NOTES
100262	1	Living Rm	N	2	switch	
100257		↓	E	4	outlet	
100280		↓	S	8	outlet	
100275		↓	N	16	switch	
100274		Hall	E	20	outlet	D=100282
100259		Kitchen	E	30	outlet	
100277		↓	W	34	outlet	
100285		Utility Rm	E	37	switch	
100281		Family Rm side of kitchen wall	NE	44	outlet	
100356		Master Bath	N	47	switch	
100362		Master BR	E	67	switch	D:100357
100360		↓	N	69	outlet	
100358		FAMILY RM	N	83	switch	
100361		GUEST BR 2	S	104	outlet	
100359		↓	N	109	switch	
100363		GUEST BR 2	N	125	outlet	
100355		↓	S	130	switch	
100279		GARAGE	N	154	switch	
~~100364~~		Guest BR 1	E	107	outlet	8"x8" ~2' No outlet
100364 (FAT)						

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

ID: 080 39FL02

PASSIVE SAMPLE FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/7/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): MED MHK WEC

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100 331	1	LR	D3	S	8/7/09	12:23	8/19/09	12:45	12D 22m
100 332	1	LR dup		D					
100 333	1	Master BR		S					
100 334	1	Guest BR		S					
100 335	1	Outdoor		S					
100 336	—	MB		MB					
100 337	1	LR	NO_2 SO_2 HF	S		12:28			17
100 338	1	LR dup		D					
100 339	1	Master BR		S					
100 340	1	Guest BR		S					
100 341	1	Outdoor		S					
100 342	—	MB		MB					
100 343	1	LR	H_2S	S		12:31			14
100 344	1	LR dup		D					
100 345	1	Master BR		S					
100 346	1	Guest BR		S					
100 347	1	Outdoor		S					
100 348	—	MB		MB					
100 349	1	LR	Aldehydes	S		12:36			9

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ID: 080 79FL02

PASSIVE SAM LE FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date:

Home Address: (b)(6)

Project#: 16512

Field Person(s): MED WHK WEC

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100 350	1	LR dup	Aldehydes	D	8/7/09	12:36	8/10/09	12:45	120 9
100 351	1	Master BR	↓	S	↓	↓	↓	↓	
100 352	1	Guest BR	↓	S	↓	↓	↓	↓	
100 353	1	Outdoor	↓	S	↓	↓	↓	↓	
100 354	—	MB	↓	MB	↓	↓	↓	↓	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ID: 080^79FL02

PASSIVE SAM_LE FIELD DATA

Page __ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Coupon

Client: CPSC

Date: 8/7/09

Home Address: (b)(6) [redacted]

Project#: 16512

Field Person(s): MED MHR WEC

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100369	1	Master Bedroom		Coupon	8/7/09		8/19/09	12:15	
100370		Living Room							
100371		Guest BR							
100372		Master BR diffuser							
100373		OUTDOOR							

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/7/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): [illegible]

Camera ID: EEAMP22

PHOTO NO.	FLOOR	LOCATION	NOTES
1-5		OUTSIDE GENERAL	
6-9		CONDENSER (b)(3):CPSA Section 6(b) MFG.	# GSH 130361A A
10-12	1	GARAGE	CMU FRONT/SIDE
15-20	1	AHU - LAUNDRY ROOM (b)(3):CPSA Section 6(b)	MFG. MOD. ARUF3642L6AA
			DX COOL / ELEC RES. HEAT
			COIL REPLACED 2/09
21		LAUNDRY ROOM	
22-23		WASHER SHUT-OFF VALVE	
24		DRYER OUTLET	
25-26		KITCHEN SINK PLATING-FAUCET	
27-29		KITCHEN SINK CU LINES	
30		REFRIGERATOR LINES	
31		MASTER BATH SINK LINES	
32		MASTER BATH TOILET SHUTOFF	
33		SHOWER BEZEL - MASTER	
34		MASTER BATH TUB SPOUT	
35		COPPER "COUPON" - MAS. BATH	
36-39		2nd BATH TUB SPOUT/BEZELS/TOILET SHUTOFF	
40		2nd BATH SINK LINES	
41-44		LR/DR AREAS	
45-49		KITCHEN / DEN AREA	
50-54		MASTER BEDROOM	
55-56		NE BEDROOM	
57		2nd BATH	
58-59		SE BEDROOM	
60		ATTIC WALLBOARD - NAT. GYP.	
61		LR OUTLET # 2	
62		DR OUTLET # 16	

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/7/09

(b)(6)

Home Address: [redacted]

Project#: 16512

Field Person(s): [redacted]

Camera ID: ECAMP22

PHOTO NO.	FLOOR	LOCATION	NOTES
63	-	E Wall outlet - Hall #	20
64		W Wall - Kitchen Outlet #	34
65		GARAGE SW - N. Wall #	154