ENVIRONMENTAL HEALTH & ENGINEERING

Environmental Health & Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

House ID 081009 fL01

Date 8/10/09

Field Technician(s) (b)(6)

House Address

General Weather Description

1. Questionnaire

1) Interviewed home owner YES NO

2) Age of the House (years) built 2001 OCC. Dec 7 2001

3) Estimated Floor Area (sqft) ~ 2,400 sf

4) Was as there any demo's to the house?

YES NO → never had hurricane dmg
vog reno.

If YES, when was it done? Please Explain.

baths + beds same → replaced ceramic floor area – (was not originally laid properly)

5) Has there been any fire in the building?

YES NO

If YES, when did it happen? Please Explain.

6) Any pesticides/herbicides been applied around the building or in the yard?

YES NO

If YES, when was it applied? Please list the type of chemicals used.

raid in dry Rm / the rest in garage
historically did pest control (not in recent yrs)

7) Has there been any recent painting/staining done in the home?

YES NO

If YES, when, where and what type of paint/stain was used?

2007 painting latex

8) Has any work been done on the AC system since construction?

YES NO

starting July 2002 replaced coils 7 times in 6 yrs in Oct. 08 when coil failed again replaced whole system. New system is a Trane. whole system,

If YES, please describe?

9) Are all the AC system components original?

YES NO See above

If NO, please describe?

10) What is the age of your refrigerator? old fridge died & was replaced in '07. Old one was ~10 yrs old. so new one is ~2 yrs

_____ years

11) Has any piping been replaced in the home?

YES NO

If YES, please describe?

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many units?

single story

2) Number of rooms

4BR 2bath, LR Fam Din

3) Above grade Construction

Wood Frame Concrete block w/ wood studs Stone Brick Other _____

4) Basement

Full Crawlspace Slab Other _____

5) Foundation

Concrete Cinder Block Stone Other_____

6) Garage

YES NO

If YES, Attached Detached

If YES, Used for Car Parking? YES NO

If YES, Any gas-powered equipment or cans of gasoline/fuels stored? YES NO Up to '05 none. fuel cans for gasoline generator (currently, empty)

(b)(3):CPSA Section 6(b)

HVAC Model 4TEC3F60B1000AA Condenser Model 4TTR3060A1000AA

that apply)

Natural Gas Fuel Oil Kerosene Electric

Propane Solar Wood Coal

Just for bbq grill

9) Water Supply

Public City of Vero Beach Well Other _____

10) Sewage

Public Septic Leach Field Other _____

11) Attic

Finished Unfinished

3. Interior Characteristics

1) Any odors upon entering the building?

YES NO faint odor

If YES, describe sulfur

2) Fireplace

YES wood-burning NO

3) Floors (circle all that apply)

Hardwood Carpet Ceramic Tile Vinyl Tile laminate in one room (office)

Unfinished Wood Unfinished Concrete Other _____

4) Walls (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

5) Ceiling (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

Data For Parcel 33400800004000000068.0

Base | Land | Sales | Sketch | Improvements | Permits | Misc | History | Trim | Tax

Sketch Data

Parcel: 33400800004000000068.0

Owner: JAMES A * ROSALIE Z WEBSTER

Site Address: (b)(6) VERO BEACH, FL 32963



[+] Map this property.

Sketch

Card: 1



Scale: 5ft

A	**OP40**	401.5 sqft
B	**OP20**	27 sqft
C	**OP30**	84 sqft
D	**OP20**	36 sqft
E	**UT50**	64 sqft
F	**GAR50**	484 sqft
G	**BASE**	2367.5 sqft

Download Sketch Codes

Report Discrepancy

Copyright ©2007 Digital Data Technologies, Inc.

GIS parcel shapefile last updated 4/27/2009 12:16:38 AM.
CAMA database last updated 4/27/2009 12:33:52 AM.

House Address (b)(6)

Page 1/



House Address (b)(6) [redacted]

Page 2



House Address (b)(6) [redacted] Page 31



(b)(6)

House Address



House Address (b)(6)

Page 5




N
HVAC
elec panel
Door
101
E
100
Car door
S
W
114
GARAGE
C175
attic access
113
water heater
112
door
110
111

ACTIVE SAMPLE FIELD DATA

Page ___ ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): [illegible] C of CF

Date: 8/10/09

Project#: 16512

ROTA ID #: ~~EG~~LTR08

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
✓ 100298		Living Rm	Inorganic	S	13501	.497	9:04	.499	12:31	209	
✓ 100374		Dup of LR		D	02818	.498		.509		210	
✓ 100295		OUTDOOR		S	07766	.498		.513		213	
✓ 100297		Master BR		S	02994	.495		.489		212	
✓ 100301		Guest BR		S	10142	.506		.495		215	
✓ 100377		Blank		FB	—	—					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAMPLE FIELD DATA

Page ___ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MGD MHK Femi CofCfx

Date: 8/10/09

Project#: 16512

ROTA ID #: EGLTR08

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
✓ 100375		Living Rm	Organic	S	12989	.501	9.04	.504	12.31	210	
✓ 100376		Dup of LR		D	13858	.510		.514		209	
✓ 100300		Outdoor		S	06737	.494		.466		213	Sample ID# 100300
✓ 100296		Master BR		S	13445	.496		.470		216	
✓ 100294		Guest BR		S	13009	.506	↓	.504		215	
✓ 100378		Blank	↓	FB	—	—					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAMPLE FIELD DATA

Page ___ ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6) Vero Beach

Field Person(s): MED MHK Femi CofCF ✓

Date: 8/10/09

Project#: 16512

ROTA ID #: EGLTRØ8

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
✓ 100306		Living Rm	Aldehyde	S	10116	.520	9:04	.524	12:31	210	
✓ 100302 100309		Dup of LR		D	10483	.503		.512		208	
✓ ~~100308~~ MED		OUTDOOR		S	06759	.503		.413 ~~.408~~		213	sample ID# 100308
✓ 100316		Master BR		S	13459	.499		.502		214	
✓ 100305		Guest BR		S	10486	.500		.491		214	
✓ 100303		Blank		FB	—	—					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAMPLE FIELD DATA

Page ___ : ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

GRAB

Client: CPSC

Home Address: (b)(6)

Field Person(s): MED WHK P

Date: 8/10/09

Project#: 16512

ROTA ID #:

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	~~ROTA READ END~~	~~END TIME~~	SAMPLE DURATION (MINS)	NOTES
100428	1	Living Rm	SULFUR	AIR	13425		17:26			.5	30 Sec Grab
100429	↓	Dup of Living Rm	↓	↓	↓		17:31			↓	↓
100430	↓	outdoors	↓	↓	↓		17:33			↓	↓
100431	↓	Master BR	↓	↓	↓		17:36			↓	↓
100432	↓	Guest BR	↓	↓	↓		17:38			↓	↓

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN ELD DATA

Page 1

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MED MHK Fenn #7=std2

Date: 8/10/09
Project#: 16512

XRF Serial #: 10452
XRF Scan Time 20 sec

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
* 3	1	Family Room	S	18 inches outlet	(finer) textured		SCAN		11:01	1389	Outlet
4			S	6 feet					11:03	159	
5			W	6 feet					11:05	272	
6			W	4 feet					11:09	370	
8			N	7 ft ~~switch~~					11:25	~~[illegible]~~ 172	
* 9			E	4' switch					11:26	339	
* 10			E	4' switch					11:26	423	
11			E	4'					11:27	420	Dup of 10
12		Foyer	S	7'					11:28	272	
13		Foyer	S	4'					11:29	369	
14		Family Rm	SW	7' above door to Office					11:29	420	
15		Family Rm	E	3'					11:30	393	
* 16		Dining Rm	W	18" outlet					11:31	406	
17			W	7'					11:32	998	
18			S	7'					11:32	354	
19			S	2'					11:33	400	
20			E	7'					11:34	1538	
21			E	7'					11:34	1523	Dup of 20
22			E	2'					11:35	1482	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN ELD DATA

Page 2 ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/10/09

Project#: 16512

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
23	1	Dining Rm	N	4' switch	Texture		SCAN		11:36	313	
24	1	↓	N	7'					11:36	430	
25	1	Kitchen	S	4' counter outlet					11:37	436	
26			W	4' " outlet					11:38	1305	
27			E	4'					11:39	360	
28			S	4' switch					11:39	318	
29			S	7' above doorway					11:40	347	
30			E	4' above stove					11:41	362	
31			E	4' " "					11:42	390	Dup of 30
32			N	7'					11:43	436	
33			SW	7' by doorway to LR					11:43	468	
34			W	18" outlet					11:44	1278	
35			N	7'					11:45	975	
36			W	4' switch					11:45	361	
37			W	7'					11:46	961	
38		Family Rm	N	7'					11:46	538	
39			N	3'					11:47	1553	
40			NE	7' above fireplace					11:47	221	
41			NE	" "					11:48	221	Dup of 40

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page 3

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): Std Z = #59

Date: 8/10/09

Project#: 16512

XRF Serial #:

XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
42	1	Living Rm	E	18" outlet	Texture		SCAN		11:49	379	
43			E	7'					11:50	1334	
44			S	18" outlet					11:51	388	
45		kitchen island	S	2'					11:51	1541	
46		kitchen island	SE	18" outlet					11:53	1201	
47		Pantry closet	E	2'					11:54	1346	
48			S	3'					11:55	1503	*
49			W	4'					11:55	1554	
50		Laundry closet	N	4'					11:56	556	
51			N	4'					11:57	538	Dup of 40
52			E	4'					11:57	432	
53			S	7'					11:58	475	
54		Laundry Rm	S	4' switch					11:59	406	
55		Laundry Rm	S	7'					12:02	377	
56		" "	E	4'					12:03	374	
57		" "	E	7'					12:04	314	
58		" "	N	7' above door					12:04	317	
~~59~~ 60		" "	N	4' by laundry machines					12:11	354	
61		" "	N	4'					12:12	353	Dup of 60

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN ELD DATA

Page ___ : ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MED MHR Tem

Date: 8/10/09

Project#: 16512

XRF Serial #:

XRF Scan Time

LOCATION ID	FLOOR	LOCATION (ROOM)	WALL COOR. N/S/E/W	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
62	1	Laundry	W	4'	Texture		SCAN		12:28	~~514~~ 332	
63		Guest BR 2 Closet	E	4'					12:28	514	
64			W	4'					12:30	506	
65			S	2'					12:57	510	
66			S	6'					12:58	516	
67		Guest BR 2	S	2'					12:59	559	
68			S	7'					1:00 pm	467	
69			W	2'					1:01	515	
70			W	7'					1:01	519	
71			W	7'					1:02	519	Dup of 70
* 72			E	4'	switch				1:02	332	
73			N	7'					1:03	492	
74			N	2'					1:04	537	
75			E	7'					1:04	458	
76			E	2'					1:05	447	
77		Bathroom	S	2'	by toilet				1:06	520	
78			S	7'	above mirror				1:07	446	
79			E	2'	by toilet				1:07 pm	366	
80			E	7'	above door				1:08	449	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page ___ : ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MED MHK Ferrie 95=Stdz

Date: 8/10/09
Project#: 16512

XRF Serial #:
XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
81	1	Bathroom	E	7'	Texture		SCAN		1:09	418	Dup of #40 above door
82			N	7' above closet					1:09	383	
83			N	4'					1:10	1833	
84			W	7' above door					1:12	341	
* 85			W	4' switch					1:12	354	
86		Bathrm Closet	N	5'					1:14	382	
87			W	4'					1:14	1637	
88			E	4'					1:15	536	
89		hall btwn Guest BRs	W	3'					1:16	522	
90			W	7' above doorway					1:16	415	
91			W	7' " "					1:17	444	Dup of 90
* 92			E	4' switch					1:18	494	
93			E	2'					1:18	492	
94		inside Guest BR Closet	S							ND	
96			S	4' ins					1:21	515	
97			E	4'					1:23	337	
98			N	4'					1:24	161	
99		Guest BR	W	7'					1:24	406	
* 100			W	18" outlet					1:25	565	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page ___ ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSL

Home Address: (b)(6)

Field Person(s): _____

Date: 8/10/09

Project#: 16512

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
* 101	1	Guest BR	W	18" outlet	Textured		SCAN		1:26	571	Dup of #100
102			N	7'					1:26	463	
* 103			N	4' switch					1:27	457	
104			E	7'					1:28	1728	
* 105			E	18" phone jack					1:28	459	
* 106			S	18" outlet					1:29	332	
107			S	7'					1:30	527	
108		Garage	E	3'					1:32	1369	
109			E	7' above door					1:33	984	
* 110			N	18" outlet					1:33	1295	
111			N	18" outlet					1:34	1336	Dup of 110
112			N	7' by water heater					1:35	1711	
113			W	7'					1:36	1899	
114		Master BR	W	3'					1:36	1279	
115			W	7'					1:39	789	
116			W	2'					1:39	530	
117			S	7'					1:40	1223	
* 118			S	4' by switch					1:41	1435	
119			E	7' above doorway					1:41	294	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page ___ ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/10/09
Project#: 16512

XRF Serial #: _____
XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
120	1	Master BR	E	2'	Textured		SCAN		142	1174	
121		" "	E	2'					143	1226	Dup of 120
(*) 122			N	4' switch					143	395	
123			NW	7' above window					144	765	
124		Master adjoining Hall to BR	E	7'					144	1032	
125		" " "	W	7'					145	1246	
126		"HER" Closet(2)	N	4'					146	1676	
127		" "	E	3'					147	1695	
128		" "	E	5'					148	927	
129		" "	S	4'					148	1343	
130		"His" closet (1)	N	5'					149	1215	
131		" "	N	5'					150	1268	Dup of 130
132		" "	W	4'					151	1504	
133		" "	W	6'					151	1401	
134		" "	S	5'					152	1166	
(*) 135		Master Bath	N	4' switch					152	1411	
136			N	7' above mirror					154	848	
137			W	7' above mirror					155	1215	
138			W	4 by bathtub					155	1560	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN ELD DATA

Page ___ : ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 8/10/09

Project#: 16512

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
139	1	Master Bath	E	7' above door	Texture		SCAN		1:56	1247	
* 140		" " WC	E	4' switch					1:57	1526	
141		" " "	E	4'					1:57	1593	
142		" " "	E	2'					1:58	1542	
143		" " "	S	2'					1:59	1400	
144		" " "	S	7'					2:00	1220	
145		" " "	W	2'					2:01	1218	
146		" " "	W	7'					2:01	878	
147		" " "	N	4'					2:02	449	
* 148		Master Bath	S	4' outlet					2:02	408	
149		" "	S	7' above tub					2:03	926	
* 150		Office	S	2' outlet					2:04	460	
151		"	S	2'					2:05	467	Dup of 150
152			S	5'					2:06	397	
153			E	6'					2:06	281	
* 154			E	4' switch					2:07	1498	
155			N	2'					2:07	1423	
156			N	6'					2:08	1323	
157			W	2'					2:09	426	
158			W	7'					2:09	308	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN ELD DATA

Page ___ ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CDS

Home Address: (b)(6)

Field Person(s): 159 = Std 2

Date: 8/10/09

Project#: 16512

XRF Serial #:

XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	~~SAMPLE SIZE~~	TIME	XRF Reading	NOTES
158	1	Office	W	7'	Texture		Scan				
C 160		Guest BR 2 closet		Ceiling					348	479	
C 161		Guest BR 2							349	371	
C 162		" "							350	423	Dup of 161
C 163		Guest Hall							351	1825	
C 164		Guest Bath							352	239	
C 165		Guest BR							353	1293	
C 166		Family Rm							356	436	
C 167		" "							358	545	
C 168		Laundry Rm							359	453	
C 169		Master BR							400	556	
C 170		Master BR Adj Hall							403	1127	
C 171		" "							403	954	Dup of 170
C 172		"HER" closet							404	1419	
C 173		Master Bath (above bathtub)		Ceiling					406	1522	
C 174		" "							407	1787	
C 175		Garage							415	1842	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

VISUAL CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPS (b)(6)

Home Address: (b)(6)

Field Person(s): MFK MED F

Date: 8/10/09

Project#: 16512

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
1	1	HVAC Condenser	N	Outdoor	1	
	1	HVAC handler	|	garage	1	
		HVAC coil	|	garage	2	
		Water Heater	↓	garage	1-2	garage
		W. master bath sink	W	master bath	1-2	
		Kitchen sink	—	Kitchen	1	
		E master bath sink	N	Master bath	1	
		sink		guest bath	1	
		Fridge water line	E	Kitchen	2	
		fridge exp. tube	E	Kitchen	2	
		Utility sink fixtures	E		1	
		Util. sink plumbing	E		1-	
	↓	household objects	—	dining room	1	
		light switch in hall	E	Guest Hall	1+	XRF-92 / 69 & 70
		outlet	W	Guest BR	1-	XRF 103 / 71
		light switch	E	Guest BR 2	1	XRF 72 / 72
		outlet	SE	Kitchen island	1	XRF 46 / 73, 74
		outlet	W	kitchen	1+	XRF 34 / 75
		switch	S	kitchen	1+	XRF 25 / 78
		switch	S	Laundry Rm	2	XRF 54 / 79, 80
		outlet	E	Family Rm	2	XRF 42 / 76, 77
		switch	E	Family Rm	2	XRF 9 / 81, 82
		outlet	N	Dining RM	2	XRF 23 / 83, 84
		outlet	W	Dining Rm	2	XRF 16 / 85
		Boiler / Water htr		Garage	—	XRF 112 / 86
		outlet	S	Living Rm	2	XRF 3 / 87, 88
		~~outlet~~	~~E~~	~~OFFICE~~	~~2~~	~~XRF 154~~ / MED
		outlet	E	Guest BR	2+	XRF / 89, 90

CORROSION RATING: 0 = No Grounding Wire, 1 = ~~No~~ Some Corrosion, 2 = ~~Some~~ Heavy Corrosion, ~~3 = Heavy Corrosion~~

VISUAL CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/10/09

Home Address: (b)(6)

Project#: 76512

Field Person(s): _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
	1	Office	E	outlet	2+	XRF 154 / 91,92,93
	1	~~Master~~ Switch	N	Masterbath	2	XRF 135 / 94,95
	1	switch	S	MasterBR	2	XRF 118 / 96,97
			N	MasterBR		XRF 122
		Outlet	N	garage	2	XRF 110

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

BULK SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC (b)(6)

Date: 8/10/09

Home Address: (b)(6)

Project#: 16572

Field Person(s): _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	LOCATION ID (SAME AS XRF LOG) & outlet or switch?	NOTES
100379	1	Family Rm	S	3 outlet	
100394	1	↓	E	9 switch	
100387		Dining Rm	W	16 outlet	
100384		Kitchen	S	25 outlet	
100395		"	W	34 outlet ~~switch~~	
100386		Living Rm	E	42 outlet	
100389		Kitchen island	SE	46 outlet	
100391		Laundry Rm	S	54 switch	
100383		Guest BR 2	E	72 switch	
100385		~~Bathroom~~ Adjoining Hall	E	92 switch	
100381		Guest BR	W	100 outlet	
100382		" "	N	103 switch	
100398		GARAGE	N	110 outlet	Dup 100380
100396		Master BR	S	118 switch	
100393		" "	N	122 switch	
100388		Master Bath	N	135 switch	
100390		Office	E	154 switch	Dup 100392
100397	↓	Dining Rm	N	23 switch	
100433		Garage by water heater	N	112 (~1.5' above 112)	8"x8"

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

~~PHOTO~~ FIELD DATA

HOBO/Q-Track

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/10/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): A

Camera ID:

PHOTO NO.	FLOOR	LOCATION	NOTES
		2412444 - living room	
		2412454 - master Bedroom	
		QT22 Living Rm	
		QT29 Bedr Rm	

081009 FL01

PASSIVE SAM E FIELD DATA

Page ___ ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Radiello

Client: CPSC

Home Address: (b)(6)

Field Person(s): MED MHK

Date: 8/10/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100 399	1	Living Rm	O_3	S	8/10/09	16:33	8/24/09	8	
100 400		Dup of LR		D					
100 401		Outdoors		S					
100 402		Master BR		S					
100 403		Guest BR		S					
100 404		Blank		MB					
100 405		Living Rm	H_2S	S		16:40			
100 406		Dup of LR		D					
100 407		Outdoors		S					
100 408		Master BR		S					
100 409		Guest BR		S					
100 410		Blank		MB					
100 411		Living RM	NO_2SO_2HF	S		16:47			
100 412		Dup of LR		D					
100 413		Outdoors		S					
100 414		Master BR		S					
100 415		Guest BR		S					
100 416		Blank		MB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

081009FL01

PASSIVE SAM E FIELD DATA

Page ___ : ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/10/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100423	1	Living Rm	Coupon	8/10/09	S	17:04	8/24/09		
		~~Dup of LR~~			~~D~~				
100424		Outdoors			S				
100425		Master BR			S				
100426		Guest BR			S				
		~~Blank~~			~~B~~				
100427		Supply Diffuser ( )			S				

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

081009FLO 1

PASSIVE SAM. .E FIELD DATA

Page ___ f ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Radiellos

Field Person(s): MED MAK F

Date: 8/10/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100417	1	Living Rm	Aldehydes	S	8/10/09	16:53	8/24/09	8	
100418		Dup of LR		D					
100419		Outdoors		S					
100420		Master BR		S					
100421		Guest BR		S					
100422		Blank		MB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/10/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): [illegible]

Camera ID: Marg.

PHOTO NO.	FLOOR	LOCATION	NOTES	
197-4465	~	Outdoor HVAC Condenser	coolant line corrosion	23
197-4466	1	outdoor HVAC Condenser ID	ID plate	24
197-4467	1	HVAC Air Handler garage	coolant line Corrosion	25
468	1	~~Air~~ HVAC Coil	"	26
469	1	HVAC coil	"	27
471		Coil ID plate		28
47H		AHU ID plate		29
475		H_2O Heater piping	corrosion	30
476		"	"	31
477		"	"	32
478		West Master Bath sink	"	33
479		East Master bath sink	"	34
480		Kitchen sink	"	35
481		Kitchen sink	"	36
483		Guest bath sink	"	37
484		Water line behind fridge	"	38
485		Fridge exp. tube	"	39
486		Fridge plumbing	"	40
487		Utility sink	"	41
488		Utility sink plumbing	"	42
489-493		household objects	"	43-46
494		Master bedroom facing the south wall	general layout	47
498		Master bedroom facing north wall	"	48
501		Master bathroom facing south west	"	49
502		Master bathroom facing the south wall	"	50
503		Living room facing the north west angle	"	51
504		Living room facing the north east angle looking into the ~~dining~~ kitchen area		52
505		Dining room facing the south wall	general layout	53

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/10/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): MHK, MEP, F

Camera ID: ~~Fomi~~ Marg

PHOTO NO.	FLOOR	LOCATION	NOTES
197-4506	1	Kitchen facing east wall	general layout 54
507		Kitchen facing south west towards the living room area	" 55
508		Family room facing north ~~east~~ wall	" 56
509		Family room facing north wall	" 57
510		Guest bed room 2 facing east wall	" 58
511		Guest bed room 2 facing south wall	" 59
512		Guest bedroom facing slider on north side	" 60
513		Guest bedroom facing south wall towards bedroom 2	" 61
514		Office facing south wall	" 62
515		Office facing north west angle	" 63
517		Office facing south west angle showing door into master bldroom	64
518		Bathroom facing east wall and door leading outside	65
519		Bathroom facing door ~~into door~~ towards west and hallway b/w guest rooms	66
520		Kitchen facing west	67
521		attic in garage, (attic floor)	"made in china" 68
563		garage outlet	corrosion 98