081709LA01

ENVIRONMENTAL HEALTH & ENGINEERING

Environmental Health & Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

House ID _____

Date 8/17/09

Field Technician(s) MAF

House Address (b)(6)

General Weather Description Hot Humid 90° F

1. Questionnaire

1) Interviewed home owner YES NO

2) Age of the House (years)

3 years old

3) Estimated Floor Area (sqft)

1630 Living Area

4) Was as there any demo's to the house?

YES NO

If YES, when was it done? Please Explain.

5) Has there been any fire in the building?

YES NO

If YES, when did it happen? Please Explain.

6) Any pesticides/herbicides been applied around the building or in the yard?

YES NO

If YES, when was it applied? Please list the type of chemicals used.

1 x per year service

7) Has there been any recent painting/staining done in the home?

YES NO

If YES, when, where and what type of paint/stain was used?

Finished in March 09 painted entire house

8) Has any work been done on the AC system since construction?

YES NO

If YES, please describe?

Moved in June of 06 coil replaced June 07 & June 08

9) Are all the AC system components original?

YES NO

If NO, please describe?

10) What is the age of your refrigerator?

3 years New / house

11) Has any piping been replaced in the home?

YES NO

If YES, please describe?

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many units?

Single family

2) Number of rooms

9

3) Above grade Construction

Wood Frame Concrete Stone Brick Other _____

4) Basement

Full Crawlspace Slab Other _____

5) Foundation

Concrete Cinder Block Stone Other_____

6) Garage

YES NO

If YES, Attached Detached

If YES, Used for Car Parking? YES NO

If YES, Any gas-powered equipment or cans of gasoline/fuels stored?

YES NO

7) Type of HVAC System

Make _____ HVAC Model _____ Condenser Model _____

8) Types of Fuel (circle all that apply)

Natural Gas Fuel Oil Kerosene Electric (Heat) Dryer Heat Fireplace

Propane Solar Wood Coal oven/stove

9) Water Supply

Public Well Other _____

10) Sewage

Public Septic Leach Field Other _____

11) Attic

Finished Unfinished

3. Interior Characteristics

1) Any odors upon entering the building?

YES NO

If YES, describe Chinese Drywall

2) Fireplace

YES NO

3) Floors (circle all that apply)

Hardwood Carpet Ceramic Tile Vinyl Tile

Unfinished Wood Unfinished Concrete Other _____

4) Walls (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

5) Ceiling (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

Kitchen / Great Room / Dining

House Address (b)(6) Mandeville, LA Page 1



House Address (b)(6) Mandeville ~~Street~~ ~~Street~~ LA

Guest Bedroom

Page 2



House Address (b)(6) Mandeville, LA Page 3



ACTIVE SAM. Ξ FIELD DATA

Page __ f ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MAF

Date: 8/17/09

Project#: 16512

ROTA ID #:

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	Vol (L)	NOTES
102177		Great Room	organic	S	13509	.50	9:20	.52		200	102	
102178		Great Room		D	7766	.50		.32		202	103	
102179		Master BR			10486	.52		.52		207	108	
102180		Guest BR			13658	.50		.53		205	106	
~~13591~~ 102181		Outdoor			13591	.49		.51	~~.51~~	203	102	
102182		FB MB		FB MB	—	—		—		—	0	
102183		Great Room	Inorganic	S	12989	.51	9:20	.55		199	105	
102184		GR		D	13445	.50		.51		202	102	
102185		Master BR			10142	.49		.50		207	102	
102186		Guest BR			13459	.50		.52		205	105	
102187		Outdoors			10483	.51		.52		203	105	
102188		FB MB		FB MB	—	—		—		—	0	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MAF

Date: 8/17/09

Project#: 16512

ROTA ID #:

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	Vol (L) NOTES
102189		Great Room	Aldehyde	S	6759	.49	9:20	.51		200	100
102190		Great Room		D	13481	.51		.48		200	100
102191		Master BR			02994	.50		.52		207	106
102192		Guest BR			02711	.51		.50		205	104
102193		Outdoors			02978	.51		.51		203	104
102194		MB		MB	—	—		—		—	0

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

AIR SAMPLING FIELD DATA

Page _ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Job Site: (b)(6)

Field Person(s): _____

Date: 8/17/09 Project#: _____

Target Analyte: _____

Passive: ( ) Active: X

SAMPLE ID	FLOOR	LOCATION	QA TYPE	PUMP ID	ROTA ID	ROTA READ ON OR DATE	TIME ON	ROTA READ OFF OR DATE	TIME OFF	PUMP DUR OR EXP TIME (MIN)	COMMENTS
102242		~~Dr~~ Great Room	S				1530				
102243		Great rm	D								
102244		Great Bedrm	S								
102245		master BR	S								
102246		OUTDOOR	S								

QA TYPES: S = Sample, D = Duplicate, R= Replicate, A = Ambient, FB = Field Blank, SB = Shipping Blank (or Media Blank)

XRF SCAI IELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: Mandeville

Home Address: (b)(6) ~~Slidell~~, LA

Field Person(s): MAF

Date: 8/17

Project#:

XRF Serial #: 10457

XRF Scan Time 20 sec

Reading ~~LOCATION~~ ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
~~1~~ 2	1	Guest BR	W	5'	wall	1			11:06	190	
3		Guest BR	W	18"	wall	2			11:08	191	outlet
4		Guest BR	~~W~~ S	4'	wall	3			11:09	228	closet
~~4~~ 5		Guest BR	S	5'	wall	4			11:11	199	
6		Guest BR	E	5'	wall	5			11:12	183	
7		Guest BR	E	18"	wall	6			11:14	224	
8		Guest BR	N	5'	wall	7			11:16	203	
9		Guest BR	N	18"	wall	8			11:17	193	outlet
10		Guest BR	N	6'	wall	9			11:17	165	
11		Master BR	S	6'	wall	10			11:20	212	
12		Master BR	S	2'	wall	~~2~~ 11			11:20	232	
13		Master BR	E	6'	wall	~~3~~ 12			11:21	189	
14		Master BR	E	2'	wall	~~4~~ 13			11:22	171	
15		Master BR	N	6'	wall	~~5~~ 14			11:23	216	
16		Master BR	N	18"	wall	~~6~~ 15			11:23	205	outlet
17		Master BR	N	18"	wall	~~7~~ 16			11:24	213	outlet
18		Master BR	W	6'	wall	~~8~~ 17			11:26	201	
19		Master BR	W	2'	wall	~~9~~ 18			11:26	234	
20		Master BR	S	6'	wall	~~10~~ 19			11:28	214	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: Vandenville

Home Address: (b)(6) Slidell, LA

Field Person(s):

Date: 8/17

Project#:

XRF Serial #:

XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
21	1	Master BR	S	3'	wall	~~11~~ 20			11:29	977	
22		Master BR	S	3'	wall	~~12~~ 21			11:29	1,003	Duplicate
23		Master BR	E	6'	wall	~~13~~ 22			11:30	1,056	
24		Master BR	E	2'	wall	~~14~~ 23			11:31	971	
25		Master BR	N	4'	wall	~~15~~ 24			11:32	884	Switch plate cover
26		Master BR	S	4'	wall	~~16~~ 25			11:33	1364	
27		Master BR	S	2'	wall	~~17~~ 26			11:34	1239	
28		Master BR	E	2'	wall	~~18~~ 27			11:35	216	
29		Master BR	W	6'	wall	~~19~~ 28			11:35	1323	
30		Master BR	W	4'	wall	~~20~~ 29			11:36	512	switch plate
31		Master BR	W	6'	wall	~~21~~ 30			11:37	128	
32		Master BR	S	6'	wall	~~22~~ 31			11:38	927	
33		Master BR	E	4'	wall	~~23~~ 32			11:38	1155	
34		Master BR	N	2'	wall	~~24~~ 33			11:39	275	
35		Master BR	W	5'	wall	~~25~~ 34			11:40	256	
36		Master BR	W	2'	wall	~~26~~ 35			11:42	1194	Bulk sample Location
37		Master BR	N	3'	wall	~~27~~ 36			11:43	1385	
38		Master BR	W	6'	wall	~~28~~ 37			11:44	1336	
39		Master BR	W	6'	wall	~~29~~ 38			11:45	1359	Duplicate

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: Mandeville

Home Address: (b)(6) Hotel, LA

Field Person(s):

Date: 8/17

Project#:

XRF Serial #:

XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
40	1	Dining	E	6'	wall	~~1~~ 39			12:01	284	
41		Dining	E	2'	wall	~~2~~ 40			12:01	668	
42		Dining	N	1'	wall	~~3~~ 41			12:02	1066	outlet
43		Dining	N	6'	wall	~~4~~ 42			12:03	167	
44		Dining	N	18"	wall	~~5~~ 43			12:03	840	outlet
45		Great Room	W	6"	wall	~~6~~ 44			12:04	431	
46		Great Room	W	18"	wall	~~7~~ 45			12:05	1209	
47		Great Room	NW	6'	wall	~~8~~ 46			12:06	359	
48		Great Room	NW	18"	wall	~~9~~ 47			12:07	623	
49		Great Room	S	6'	wall	~~10~~ 48			12:08	630	
50		Great Room	S	18"	wall	~~11~~ 49			12:08	1007	Outlet
51		Foyer	E	6'	wall	~~12~~ 50			12:09	174	
52		Foyer	E	18"	wall	~~13~~ 51			12:10	852	outlet
53		Foyer	W	6'	wall	~~14~~ 52			12:11	324	
54		Foyer	W	6'	wall	~~15~~ 53			12:11	354	Duplicate
55		Foyer	W	18"	wall	~~16~~ 54			12:12	648	
56		Kitchen	SE	3'	wall	~~17~~ 55			12:14	976	
57		Kitchen	S	4'	wall	~~18~~ 56			12:14	825	
58		Kitchen	W	4'	wall	~~19~~ 57			12:16	1018	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: Mandeville

Home Address: (b)(6) Ticket, LA

Field Person(s):

Date: 8/17

Project#:

XRF Serial #:

XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
59		Kitchen	W	6'	wall	~~20~~ 58			12:18	173	
60		Kitchen	S	6'	wall	~~21~~ 59			12:19	538	
61		Kitchen	E	6'	wall	~~22~~ 60			12:20	1032	
62		Kitchen	S	6'	wall	~~23~~ 61			12:21	247	
63		Garage	N	6'	wall	~~24~~ 62			12:22	717	
64		Garage	N	18"	wall	~~25~~ 63			12:23	1306	outlet
65		Garage	~~W~~ S	6'	wall	~~26~~ 64			12:24	440	
66		Garage	~~W~~ S	18"	wall	~~27~~ 65			12:25	1190	outlet
67		Garage	W	6'	wall	~~28~~ 66			12:26	785	
68		Garage	W	6'	wall	~~29~~ 67			12:27	773	Duplicate
69		Garage	W	18"	wall	~~30~~ 68			12:27	1067	outlet
70		Study	S	6'	wall	~~31~~ 69			12:30	210	
71		Study	S	18"	wall	~~32~~ 70			12:30	229	outlet
72		Study	N	6'	wall	~~33~~ 71			12:31	204	
73		Study	N	3'	wall	~~34~~ 72			12:32	200	
74		Study	E	4'	wall	~~35~~ 73			12:33	203	
75		Study	W	4'	wall	~~36~~ 74			12:34	220	
76		Wash/Dryer	S	6'	wall	~~37~~ 75			12:35	209	
77		Wash/Dry	S	6'	wall	~~38~~ 76			12:36	192	Duplicate

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAI IELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: Mandeville

Home Address: (b)(6) Slidell, LA

Field Person(s):

Date: 8/17

Project#:

XRF Serial #:

XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
78	1	Wash / Dry	N	6'	Wall	~~39~~ 77			12:36	211	
79		Wash / Dry	N	2'	Wall	~~40~~ 78			12:37	220	
80		Wash / Dry	E	4'	Wall	~~41~~ 79			2:06	156	
83		Great Room	W	6'	Wall	~~42~~ 80			2:41	217	
84		Great Room	W	18"	Wall	~~43~~ 81			2:41	198	Outlet
85		Great Room (Bath)	E	4'	Wall	~~44~~ 82			2:42	208	
86		Great Room (Bath)	S	~~4~~ 6'	Wall	~~45~~ 83			2:43	1499	
87		Great Room (Bath)	S	2'	Wall	~~46~~ 84			2:43	218	
88		Great Room (Bath)	N	6'	Wall	~~47~~ 85			2:44	1480	
89		Great Room (Bath)	N	2'	Wall	~~48~~ 86			2:45	213	
90		Great Room (Bath)	W	6'	Wall	~~49~~ 87			2:46	1521	
91		~~Great R~~ Kid's Room	W	6'	Wall	~~50~~ 88			2:47	201	
92		Kid's Room	W	2'	Wall	~~51~~ 89			2:47	202	
93		Kid's Room	N	6'	Wall	~~52~~ 90			2:48	202	
94		Kid's Room	N	6'	Wall	~~53~~ 91			2:48	220	Duplicate
95		Kid's Room	N	2'	Wall	~~54~~ 92			2:49	466	
96		Kid's Room	S	6'	Wall	~~55~~ 93			2:50	728	
97		Kid's Room	S	18"	Wall	~~56~~ 94			2:51	695	Outlet
98		Kid's Room	E	6'	Wall	~~57~~ 95			2:51	436	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAI IELD DATA C=Ceiling

Page __ of ___

6 of 7

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: (b)(6) Mandeville

Home Address: Slidel, LA

Field Person(s): _____

*C=Ceiling

Date: 8/17

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
99	1	Kid's Room	E	2'	Wall	~~58~~ 96			2:52	168	
100		~~Ga~~ Garage	Ceiling	Ceiling	Wall	~~59~~ 97			2:57	1092	
101		Garage	C*	Ceiling	C	~~60~~ 98			2:59	1142	Duplicate
102		Garage	C	Ceiling	C	~~61~~ 99			3:00	1099	
103		Dining Hallway	C	Ceiling	C	~~62~~ 100			3:02	249	
104		Dining Hallway	E	6'	Wall	~~63~~ 101			3:02	184	
105		Dining Hallway	E	18"	Wall	~~64~~ 102			3:03	197	outlet
106		Wash / Dry	C	Ceiling	C	~~65~~ 103			3:04	205	
107		Study	C	Ceiling ~~(High)~~	C	~~66~~ 104			3:05	341	
108		Master BR	C	Ceiling (High) ~~(Low)~~	C	~~30~~ 105			3:06	1613	
109		Master BR	C	Ceiling (Low) ~~(High)~~	C	~~31~~ 106			3:07	1324	
110		Master BR	C	Ceiling (High)	C	~~32~~ 107			3:08	1714	
111		Master BR	C	Ceiling (Low)	C	~~33~~ 108			3:08	786	
112		Master BR	C	Ceiling	C	~~34~~ 109			3:09	420	
113		Master BR	C	Ceiling	C	~~35~~ 110			3:09	210	
115		Dining	C	Ceiling	C	~~36~~ ~~67~~ 111			3:13	881	
116		Kitchen	C	Ceiling	C	~~68~~ 112			3:14	633	
117		Great Room	C	Ceiling	C	~~69~~ 113			3:16	1046	
118		Great Room	C	Ceiling	C	~~70~~ 114			3:16	933	Duplicate

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: Mandeville

Home Address: (b)(6) Metairie, LA

Field Person(s):

* C = Ceiling

Date: 8/17

Project#:

XRF Serial #:

XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
119	1	Great Room	C*	Ceiling	C	~~71~~ 115			3:17	882	
~~201~~ 120		Great Room (Bath)	C	Ceiling	C	~~72~~ 116			3:18	1043	
121		~~Gr~~ Kid's Room	C	Ceiling	C	~~73~~ 117			3:19	~~12~~ 694	
122		Kid's Room	C	Ceiling	C	~~74~~ 118			3:20	7~~17~~	
123		Guest Room	C	Ceiling	C	~~10~~ 119			3:21	313	
124		Guest Room	C	Ceiling	C	~~11~~ 120			3:23	906	
125		Guest Room	C	Ceiling	C	~~12~~ 121			3:24	948	
126		Guest Room	C	Ceiling	C	~~13~~ 122			3:25	949	Duplicate

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

VISUAL CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: (b)(6) Mandeville

Home Address: Slidel, LA

Field Person(s):

Date: 8/17

Project#:

LOCATION ID (A)	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
1 A	1	Foyer	E	102204	2	Photo# 297, 298, 299
2 A	1	Master Bedroom	N	102199	2	P# 300
~~3~~	~~1~~	~~Master Bath~~	~~S~~			
3 A	1	~~Comp. Room~~ Study	S	102198	2	P# 301, 302
4 A	1	Laundry Room	E		1	P# 303
5 A	1	~~Great Room~~ Dining	N	102203	3	P# 304, 305
6 A	1	Kitchen	E		3	P# 306
7 A	1	Guest Room	N	102209	1	P# 307
8 A	1	Secondary Bedroom Hall	W		2	P# 308
9 A	1	Great Room	S	102206/102207	3	P# 309
10 A	1	Child's Room	S	102211	2	P# 310
11 A	1	Guest Bedroom	W	102210	1	P# 311
12 A	1	Garage	N	102195	3	P# 312
13 A	1	Garage	W	102196	3	P# 313
14 A	1	Garage	S	102197	3	P# 314, 315
15 A	1	Master Bedroom	E		1	P# 316
16 A	1	Master Bed	N	102201/102202	1	P# 317
17 A	1	Great Room	N	102205	3	P# 318
18 A	1	Kitchen	N		3	P# 319
19 A	1	Kitchen	W		3	P# 320
20 A	1	Great Room	W		3	P# 321

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

BULK SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: (b)(6) Mandeville

Home Address: Lidet, LA

Date: 8/17

Project#: _____

Field Person(s): _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	LOCATION ID (SAME AS ~~XRF LOG~~) Visual Corrosion Inspection	NOTES
102195	1	Garage	N	~~25~~ 12A	
102196		Garage	W	~~30~~ 13A	
102197		Garage	S	~~27~~ 14A	
102198		Study	S	~~32~~ 3A	
102199		Master BR	N	~~76~~ 2A	
* 102200		Master BR	N	~~7~~ ?	
102201		Master BR	N	~~15~~ 16A	
102202		Master BR	N	~~15~~ 16A	Duplicate
102203		Dining	N	~~3~~ 5A	
102204		Dining Hallway	E	~~64~~ 1A	
102205		Dining	N	~~75~~ (No XRF scan)	17A
102206		Great Room	S	~~11~~ 9A	
102207		Great Room	S	~~11~~ 9A	Duplicate
102208		Great Room	W	~~43~~ 20A	
102209		Guest Room	N	~~8~~ 7A	
102210		Guest BR	W	~~2~~ 11A	
102211		Kid's Room	S	~~56~~ 10A	
102212		Master BR Closet	S	8in. x 8in. (~~16~~)	25

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

HOBOS

Client: CPSC

Home Address: (b)(6)

Field Person(s): MAF

Date: 8/17/09

Project#:

ROTA ID #:

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
2415753		Great Room									
2415752		Master BR									
2415762		Guest BR									

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

ENVIRONMENTAL HEALTH & ENGINEERING
Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Q TRAK

Date: _____
Project#: _____

Home Address: _____

ROTA ID #: _____

Field Person(s): _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
30120		Great Room									
30058		Master BR									
30045		Guest BR									

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6) MER

Field Person(s): TMM

Date: _____

Project#: 16512

	SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓	103195		LIVING ROOM	OZONE	S	9/8/09	1655	9/21/09	5:41 PM	
✓	103196		DUPLICATE	↓	D	↓	↓	↓	↓	
✓	103197		OUTDOORS	↓	S	↓	↓	↓	↓	
✓	103198		GUEST	↓	S	↓	↓	↓	↓	
✓	103199		MASTER	↓	S	↓	↓	↓	↓	
✓	103200		—	—	FB	—	—	—	—	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Page ___ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

081709LA01

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date: 9/8/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES 8/17/09
✓ ~~103201~~ 103212		LIVING ROOM 63433	COUPON	S	9/8/09	1655	9/21/09	5:41 PM	102238
✓ ~~103202~~ 103213		OUTDOOR 63434							102240
✓ ~~103203~~ 103214		GUEST 63436							102239
✓ ~~103204~~ 103215		MASTER 63438							102237
✓ ~~103205~~ 103216		SUPPLY 63437							102241
		HOBOS ON @ 1655 ON 9/8/09							
	✓	2415762 - LR							
	✓	2415753 - GUEST							
	✓	2415752 - MASTER							
									Coupon #
✓ 102240		Outdoor	Coupon				9/21/09	5:47 PM	63135
✓ 102238		Living Room			8/17/09				63134
✓ 102237		Master BR							63154
✓ 102239		Guest BR							63155
✓ 102241		Supply							63136

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date: 9/8/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ 103177		LIVING ROOM	H_2S	S	9/8/09	1655	9/21/09	5:41 PM	
✓ 103178		DUPLICATE		D					
✓ 103179		OUTDOORS		S					
✓ 103180		GUEST		S					
✓ 103181		MASTER		S					
✓ 103182				FB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date: 9/8/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ 103183		LIVING ROOM	ALDEHYDE	S	9/8/09	1655	9/21/09	5:41 pm	
✓ 103184		DUPLICATE	↓	D	↓	↓	↓	↓	
✓ 103185		OUTDOORS	↓	S	↓	↓	↓	↓	
✓ 103186		GUEST	↓	S	↓	↓	↓	↓	
✓ 103187		MASTER	↓	S	↓	↓	↓	↓	
✓ 103188	—	—	—	FB	—	—	—	—	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date: 9/8/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ 103189		LIVING ROOM	NO_2 SO_2 HF	S	9/8/09	1655	9/21/09	5:41 pm	
✓ 103190		DUPLICATE		D					
✓ 103191		OUTDOORS		S					
✓ 103192		GUEST		S					
✓ 103193		MASTER		S					
✓ 103194				FB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/17/09

Home Address: (b)(6) Slidel, LA

Project#: 16512

Field Person(s): MAF

Camera ID: MAF

PHOTO NO.	FLOOR	LOCATION	NOTES
267-69		House	
270		Cond	
271		↓	
272		Cond ID	
273		Cond ID	
274		Guest Bath	
275		Guest BR Light	
276		Master Bath Shower Head	
277		Master Bath toilet	
278		Back of Fridge	
279		"	