ENVIRONMENTAL HEALTH & ENGINEERING

Environmental Health & Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

House ID 081909LA01

Date 8/19/09

Field Technician(s) MAF

House Address (b)(6)

General Weather Description Hot Humid

1. Questionnaire

1) Interviewed home owner YES NO

2) Age of the House (years)

Built 2006 moved in 2007

3) Estimated Floor Area (sqft)

1700 sq feet

4) Was as there any demo's to the house?

YES NO

If YES, when was it done? Please Explain.

5) Has there been any fire in the building?

YES NO

If YES, when did it happen? Please Explain.

6) Any pesticides/herbicides been applied around the building or in the yard?

YES NO

If YES, when was it applied? Please list the type of chemicals used.

Termite around house

7) Has there been any recent painting/staining done in the home?

YES NO

If YES, when, where and what type of paint/stain was used?

_____.

8) Has any work been done on the AC system since construction?

YES NO

If YES, please describe?

replace coil 2years ago

9) Are all the AC system components original?

YES NO

If NO, please describe?

new coil

10) What is the age of your refrigerator?

2003 years it was in there old house also

11) Has any piping been replaced in the home?

YES NO

If YES, please describe?

_____.

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many units?

_____.

2) Number of rooms

3 bed 2.5 bath (5)

_____.

3) Above grade Construction

Wood Frame Concrete Stone Brick Other _____

4) Basement

Full Crawlspace Slab Other _____

5) Foundation

Concrete Cinder Block Stone Other_____

6) Garage

YES NO

If YES, Attached Detached

If YES, Used for Car Parking? YES NO

If YES, Any gas-powered equipment or cans of gasoline/fuels stored?

YES NO

7) Type of HVAC System

_____.

Make _____ HVAC Model _____ Condenser Model _____

8) Types of Fuel (circle all that apply)

Natural Gas Fuel Oil Kerosene Electric

Propane Solar Wood Coal

9) Water Supply

Public Well Other _____

10) Sewage

Public Septic Leach Field Other _____

11) Attic

Finished Unfinished

3. Interior Characteristics

1) Any odors upon entering the building?

YES NO

If YES, describe Burt Match / Chinese Drywall

2) Fireplace

YES NO

3) Floors (circle all that apply)

Hardwood Carpet Ceramic Tile Vinyl Tile

Unfinished Wood Unfinished Concrete Other _____

4) Walls (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

5) Ceiling (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

House Address (b)(6) Mandeville, LA Page 1

Master BR



House Address (b)(6) Mandeville LA Page 3



House Address (b)(6) Mandeville, LA

Page 4



House Address (b)(6) Mandeville, LA Page 2 Great Room / Dining / Kitchen



ACTIVE SAMPLE FIELD DATA

Page ___ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) [redacted] ...deville, LA

Field Person(s): _____

Date: 8/19

Project#: _____

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	Vol (L)	NOTES
~~120~~												
102304		Great Room	Organic	S	07778	.50	8:58	.51	12:23	200	101	
102305		Great Room	Organic	D	06759	.50	8:58	.53	12:23	200	103	
102306		Master BR	Organic		07766	.49	8:58	.50	12:23	202	100	
102307		BR #2	Organic		06737	.50	8:58	.47	12:23	205	99	
102308		Outside	Organic		10486	.49	8:58	.52	12:23	200	101	
102309		Great Room	Inorganic	S	13481	.51	8:58	.54	12:23	200	105	
102310		Great Room	Inorganic	D	13459	.50	8:58	.53	12:23	200	103	
102311		Master BR	Inorganic		10483	.51	8:58	.55	12:23	202	107	
102312		BR #2	Inorganic		13858	.50	8:58	.51	12:23	205	104	
102313		Outside	Inorganic		02978	.50	8:58	.40	12:23	182	82	
102314		Great Room	Aldehyde	S	02994	.50	8:58	.53	12:23	200	103	
102315		Great Room	Aldehyde	D	~~10~~ 13009	.51	8:58	.52	12:23	200	103	
102316		Master BR	Aldehyde		12984	.51	8:58	.53	12:23	202	105	
102317		BR #2	Aldehyde		13501	.49	8:58	.50	12:23	205	101	
102318		Outside	Aldehyde		10142	.51	8:58	.52	12:23	200	103	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

~~PASSIVE SAMPLE~~ FIELD DATA

Page ___ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Sulfer Bags

Client: (b)(6)

Home Address: Mandeville, LA

Date: 8/19

Project#: ___

Field Person(s): ___

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
102023	1	Great Room	Sulfer	S					
102024	1	Great Room	Sulfer	D					
102025	1	Outdoors	Sulfer	S					
102026	1	Master BR	Sulfer	S					
102027	2	Bedroom #2	Sulfer	S					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: (b)(6)

Home Address: Mandeville, LA

Field Person(s): _____

Date: 8/19

Project#: _____

XRF Serial #: 10452

XRF Scan Time 30 Sec

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
2	1	Master BR	N	6'	wall	~~2~~ 1			10:35	450	
3		Master BR	W	6'	wall	2			10:35	166	
4		Master BR	S	2'	wall	3			10:36	1113	
5		Master BR	N	6'	wall	4			10:36	1201	
6		Master BR	N	2'	wall	5			10:37	1044	
7		Master BR	E	6'	wall	6			10:38	456	
8		Master BR	E	2'	wall	7			10:38	665	
9		Master BR	N	6'	wall	8			10:39	675	
10		Master BR	W	6'	wall	9			10:40	1293	
11		Master BR	W	6'	wall	10			10:40	~~116~~ 637	Observed paint bubbling
12		Master BR	W	6'	wall	11			10:41	304	Duplicate
13		Master BR	E	6'	wall	12			10:42	761	
14		Master BR	S	6'	wall	13			10:44	474	
15		Master BR	N	6'	wall	14			10:45	175	
16		Master BR	N	18"	wall	15			10:46	1141	out let
17		Master BR	W	6'	wall	16			10:47	247	
18		Master BR	W	2'	wall	17			10:47	874	
19		Master BR	E	6'	wall	18			10:48	263	
20		Master BR	E	18"	wall	19			10:49	169	outlet

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAI IELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) , Mandeville, LA

Field Person(s): _____

Date: 8/19

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
21	1	Master BR	S	6'	wall	20			10:51	744	
22		Master BR	S	18"	wall	21			10:51	1255	outlet
23		Great Room	S	6'	wall	22			10:53	182	
24		Great Room	E	6'	Wall	23			10:53	1380	
25		Great Room	SW	6'	wall	24			10:54	1055	
26		Great Room	W	6'	wall	25			10:54	418	
27		Great Room	W	2'	wall	26			10:55	219	
28		Great Room	W	2'	wall	27			10:56	283	Duplicate
29		~~Great Room~~ Dining	W	6'	wall	28			10:56	1188	
30		Dining	W	2'	wall	29			10:58	394	
31		Dining	N	4'	wall	30			10:58	949	
32		~~Dining~~ Kitchen	N	6'	wall	31			10:59	717	
33		Bath	N	6'	wall	32			11:00	247	
34		Bath	E	2'	wall	33			11:01	732	
35		Bath	S	6'	wall	34			11:01	224	
36		Kitchen	E	2'	wall	35			11:01	1336	
37		Kitchen	S	6'	wall	36			11:02	1305	
38		Kitchen	E	4'	wall	37			11:03	215	
39		Kitchen	E	6'	wall	38			11:04	347	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/19

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
~~39~~ 40	1	Kitchen	W	2'	wall	39			11:06	282	
41		Kitchen	E	6'	wall	40			11:06	1212	
42		Kitchen	E	6'	wall	41			11:07	418	
43		Kitchen	E	2'	wall	42			11:07	812	
44		Garage	S	6'	wall	43			11:11	1334	
45		Garage	E	6'	wall	44			11:12	198	
46		Garage	E	6'	wall	45			11:12	1356	
47		Garage	W	6'	wall	46			11:12	1485	
48		Garage	W	18"	wall	47			11:13	1297	out of
49		Great Room	E	6'	wall	48			11:16	272	
50		Great Room	W	6'	wall	49			11:17	1262	
51	2	2nd Floor Stairs	E	6'	wall	50			11:18	1042	
52		2nd Floor	N	2'	wall	51			11:19	286	
53		BR #2	N	6'	wall	52			11:20	227	
54		BR #2	N	18"	wall	53			11:20	1086	
55		BR #2	S	2'	wall	54			11:21	1906	Utility Closet; "Made in China" Marking
56		BR #2	S	6'	wall	55			11:21	1984	
57		BR #2	S	6'	wall	56			11:22	1946	Duplicate
58		BR #2	E	6'	wall	57				259	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/19

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
59	2	BR #2	E	2'	wall	58			11:29	765	
60	2	BR #2	S	6'	wall	59			11:30	1421	
61	2	BR #2	S	18"	wall	60			11:30	1162	outlet
62	2	BR #2	W	6'	wall	61			11:31	426	
63	2	BR #2	W	4'	wall	62			11:32	1273	
64	2	BR #2	S	6'	wall	63			11:32	1602	
65	2	BR #2	E	6'	wall	64			11:33	1468	
66	2	BR #2	S	2'	wall	65			11:33	486	
67	2	BR #2	E	2'	wall	66			11:34	1548	
68	2	BR #2	E	6'	wall	67			11:36	168	
69	2	BR #2	E	6'	wall	68			11:36	150	Duplicate
70	2	BR #2	E	~~6'~~ 2'	wall	69			11:37	1338	
71	2	BR #2	W	6'	wall	70			11:37	193	
72	2	~~BR #2~~ Study	S	6'	wall	71			11:38	896	
73	2	~~BR #2~~ Study	N	6'	wall	72			11:39	345	
74	2	~~BR #2~~ Study	N	18"	wall	73			11:40	1233	outlet
75	2	~~BR #2~~ Study	W	6'	wall	74			11:41	655	
76	2	~~BR #2~~ Study	W	~~6~~ 2'	wall	75			11:42	1119	
77	2	~~BR #2~~ Study	W	2'	wall	76			11:43	1201	Duplicate

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

*C = Ceiling

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: ~~9/18~~ 8/19

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
78	2	Study	S	6'	wall	77			11:43	254	
79	2	Study	S	2'	wall	78			11:44	560	
80	2	Study	N	6'	wall	79			11:44	1250	
81	2	Study	S	6'	wall	80			11:45	274	
82	2	Study	S	2'	wall	81			11:46	444	
83	2	Study	E	6'	wall	82			11:46	863	
84	2	Study	E	18"	wall	83			11:47	1177	outlet
85	2	2nd Floor Hallway	E	6'	wall	84			11:53	1141	
86	2	2nd Floor Hallway	E	18"	wall	85			11:53	10:24	outlet
87	2	2nd Floor Hallway	W	6'	wall	86			11:54	291	
88	2	2nd Floor Hallway	W	2'	wall	87			11:55	297	
~~8~~90	1	Great Room	C*	C	C	88			1:50	1133	
91	1	~~Gr~~ Kitchen	C	C	C	89			1:51	616	
92	1	Kitchen	C	C	C	90			1:51	628	Duplicate
93	1	Kitchen (Bath)	C	C	C	91			1:52	1215	
94	1	Dining	C	C	C	92			1:54	1297	
95	1	Great Room	C	C	C	93			1:56	1297	
96	1	Great Room	C	C	C	94			1:58	198	
97	1	Great Room	C	C	C	95			1:58	1279	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

*C = Ceiling

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/19

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
98	1	Master BR	C*	C	C	96			2:00	1236	
99	1	Master BR	C	C	C	97			2:00	1160	
100	1	Master BR	C	C	C	98			2:02	1354	
101	1	Master BR	C	C	C	99			2:02	1416	
102	1	Master BR	C	C	C	100			2:04	1051	
103	1	Master BR	C	C	C	101			2:06	971	
104	1	Garage	C	C	C	102			2:10	1012	
105	1	Garage	C	C	C	103			2:11	1263	Duplicate
106	1	Garage	C	C	C	104			2:12	475	
107	2	2nd Floor (Hallway)	C	C	C	105			2:16	1191	
108	2	2nd Floor (Hallway)	C	C	C	106			2:16	1325	
109	2	~~2nd Floor~~ BR #2	C	C	C	107			2:17	1226	
110	2	Bedroom #2	C	C	C	108			2:18	1356	
111	2	Bedroom #2	C	C	C	109			2:19	548	
112	2	Study	C	C	C	110			2:21	1482	
113	2	Study	C	C	C	111			2:22	226	
114	2	Study	C	C	C	112			2:23	228	Duplicate

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

VISUAL CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ Mandeville, LA Date: 8/19

Home Address: (b)(6) Project#: _____

Field Person(s): _____ *Duplicate: 102021

LOCATION ID	FLOOR	LOCATION	WALL COOR.	~~SAMPLE LOCATION~~ Bank I.D.	CORROSION RATING	NOTES
1A	1	Garage	W	102327	3	Photo # 43/44
2A	1	Garage	S	102326	3	P# 45
3A	2	Study	W	102324	3	P# 46/47 Note: Ground wire is off screw
4A	2	Study	S	102325	3	P# 48
5A	2	Hallway	E	102319	3	P# 49
6A	2	Bedroom #2	N	102327	3	P# 50/51
7A	2	Bedroom # 2	S	102322	3	P# 52
8A	2	Hallway	N	102320	3	P# 53-55
9A	2	Utility Closet	S		2	P# 56/57/58 Socket not in drywall near it.
10A	2	Bathroom	N	102323	3	P# 59
11A	1	Master Bedroom	N	102328/102329	3	P# 60/61 Dup.
12A	1	"	E	102331	3	P# 62 Homeowner left penny
13A	1	"	N	102330	3	P# 63/64
14A	1	Master Bathroom	W	102332	3	P# 65
15A	1	"	N	102333	3	P# 66
16A	1	"	N	102334	3	P# 67/68
17A	1	Kitchen	N	102335	3	P# 69
18A	1	"	S	102336	3	P# 70
19A	1	Great Room	N	*	3	P# 71/72
20A	1	" "	E	102017	3	P# 73
21A	1	" "	S	102018	3	P# 74
22A	1	" "	S	*~~102019~~ 102020*	3	P# 75
23A	1	" "	E	102019	3	P# 76
24A	1	" "	W		3	P# 77-79
25A	2	BR #2 (Closet)	S	102022	–	8" x 8"

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

~~ACTIVE~~ SAM. .E FIELD DATA

Q Trak

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/19

Project#: _____

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
30120	1	Great Room	CO2								
30045	1	Master Bedroom	CO2								
30058	2	Bedroom #2	CO2								

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

~~ACTIVE~~ SAMPLE FIELD DATA

Page ___ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Hobo

Client: _____ (b)(6)

Home Address: _____ Vinderville, LA

Field Person(s): _____

Date: 8/19

Project#: _____

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
#2415766	1	Master Bedroom	Temp/RH								
#2415761	1	Great Room	↓								
#2415765	2	Bedroom #2	↓								

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

A Outdoors exposed to gas grill ≈ 2x

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

0819091A01

977

Client: CPSC

Home Address: (b)(6)

Date: 9/8/09

Project#: 16512

Field Person(s): TMM

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ 103206	1	LIVING ROOM	H_2S	S	9/8/09	15:35	9/21/09	3:40 pm	
✓ 103207		DUPLICATE		D					
A ✓ 103208		OUTDOORS		S					Exposed to gas grill
✓ 103209	2	GUEST		S					
✓ 103210	1	MASTER		S					
✓ 103211				FB					
✓ 106878				MB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

PASSIVE SAMPLE FIELD DATA

978

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date: 9/8/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
106657	1	LIVING ROOM	ALDEHYDE	S	9/8/09	1535	9/21/09	3:48 p.m	
106658	↓	DUPLICATE	↓	D	↓	↓	↓	↓	
106659	↓	OUTDOORS	↓	S	↓	↓	↓	↓	Exposed to gas grill
106660	2	GUEST	↓	S	↓	↓	↓	↓	Exp
106661	1	MASTER	↓	S	↓	↓	↓	↓	
106662	—	—	—	FB	—	—	—	—	
106879	—	—	—	MB	—	—	—	—	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Page ____ of ____

979

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date: 9/8/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
106663	1	LIVING ROOM	NO_2 SO_2 HF	S	9/8/09	1535	9/21/09	3:40pm	
106667 ~~106664~~		DUPLICATE		D					
106664 ~~106665~~ TM		OUTDOORS		S					Exposed to gas grill
106665 ~~106666~~	2	GUEST		S					
106666 ~~106667~~	1	MASTER		S					
106668				FB					
106880				MB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

PASSIVE SAMPLE FIELD DATA

980

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date: 9/8/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ 106669	1	LIVING ROOM	OZONE	S	9/8/09	1535	9/21/09	3:40 pm	
✓ 106670	↓	DUPLICATE	↓	D	↓	↓	↓	↓	
✓ 106671	↓	OUTDOORS	↓	S	↓	↓	↓	↓	Exposed to gas grill
✓ 106672	2	GUEST	↓	S	↓	↓	↓	↓	
✓ 106673	1	MASTER	↓	S	↓	↓	↓	↓	
✓ 106674	—	—	—	FB	—	—	—	—	
✓ 106881	—	—	—	MB	—	—	—	—	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

PASSIVE SAMPLE FIELD DATA

081909LA01

981

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date:

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ ~~103201~~ ~~103212~~	1	LIVING ROOM	COUPON	S	9/8/09	1535	9/21/09	3:40 PM	63439
✓ ~~103202~~ ~~103213~~	G	OUTDOOR							63440 Exposed to gas grill
✓ ~~103203~~ ~~103214~~	2	GUEST							63380
✓ ~~103204~~ ~~103215~~	1	MASTER							63378
✓ ~~103205~~ ~~103216~~	~~2~~ 1	SUPPLY (~~BATH~~) kitchen							63381
		HOBOS ON @ 15:35 PM ON 9/8/09 off @ 3:40 PM on 9/21/09							
	✓	2415761 - LR							
	✓	2415766 - MASTER							
	✓	2415765 - GUEST							

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville LA

Field Person(s): _____

Date: 8/19

Project#: _____

Camera ID: _____

PHOTO NO.	FLOOR	LOCATION	NOTES
1	1	House #	
2	1	House Front	
3	1	House Side	
4	1	House Back	
5	1	Master Bedroom Sample location	
6	1	Great Room " "	
7	1	out door " "	
8	2	Bedroom #2 " "	
9	1	Shower head (Master Bath)	
10	1	Top of mirror (Master Bath)	
11	1	Sink Pipes #1 (" ")	
12	1	" " #2 (" ")	
13	1	Brass dishes (Master Bedroom)	
14/15 ~~14~~	1	Homeowner Penny corrosion Test	
16 ~~15~~	1	Sink Pipes (Half Bath)	
17 ~~16~~	1	Copper Pipes to Toilet (Half Bath)	
18 ~~17~~	1	Toilet Pipes (Master Bath)	
19 ~~18~~	2	Shower head (Bedroom #2 Bath)	
20 ~~19~~	2	Toilet Pipes (" ")	
21 ~~20~~	2	Sink Pipes (" ")	
22 ~~21~~	2	Storage Room Visible drywall	
23/24	2	Air handler ID	
25	2	Uninsulated Refrig line	
26	2	Iron Pipe for gas	
27	2	Attic Visible Drywall	
28-30	2	Hot water heater ID	
31	2	Rusty natural gas pipe	
32	2	Ground Wire for natural gas	

PHOTO FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/19

Project#: _____

Camera ID: _____

PHOTO NO.	FLOOR	LOCATION	NOTES
33-35	2	Air handler Coil	Coated Coil
36/37	~~3~~ Attic	Air handler ID	Air Handler for 2nd floor
38-41	Attic	Air handler coil	2nd Floor Coil is Coated
42	Attic	Drywall cieling board	Marked "Made in China"