ENVIRONMENTAL HEALTH & ENGINEERING

Environmental Health & Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

House ID 082109LA01

Date 8-21-09

Field Technician(s) NAF

House Address (b)(6)

General Weather Description Hot Humid

1. Questionnaire

1) Interviewed home owner (YES) NO

2) Age of the House (years)

4 years old

3) Estimated Floor Area (sqft)

Living 7258, 1778 garage

4) Was as there any demo's to the house?

YES (NO)

If YES, when was it done? Please Explain.

5) Has there been any fire in the building?

YES (NO)

If YES, when did it happen? Please Explain.

6) Any pesticides/herbicides been applied around the building or in the yard?

(YES) NO

If YES, when was it applied? Please list the type of chemicals used.

Standard pest control

7) Has there been any recent painting/staining done in the home?

YES NO

If YES, when, where and what type of paint/stain was used?

_____.

8) Has any work been done on the AC system since construction?

YES NO

If YES, please describe?

_____.

9) Are all the AC system components original?

YES NO

If NO, please describe?

_____.

10) What is the age of your refrigerator?

4 years

11) Has any piping been replaced in the home?

YES NO

If YES, please describe?

_____.

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many units?

_____.

2) Number of rooms

17.

3) Above grade Construction

Wood Frame Concrete Stone Brick - veneer Other _____

4) Basement

Full Crawlspace Slab Other _____

5) Foundation

Concrete Cinder Block Stone Other_____

6) Garage

YES NO

If YES, Attached Detached

If YES, Used for Car Parking? YES NO

If YES, Any gas-powered equipment or cans of gasoline/fuels stored?

YES NO

7) Type of I (b)(3):CPSA Section 6(b)

3

_____.

Make _____ HVAC Model _____ Condenser Model _____

8) Types of Fuel (circle all that apply)

Natural Gas Fuel Oil Kerosene Electric

Propane Solar Wood Coal

9) Water Supply

Public Well Other _____

10) Sewage

Public Septic Leach Field Other _____

11) Attic

Finished Unfinished

3. Interior Characteristics

1) Any odors upon entering the building?

YES NO

If YES, describe _____

2) Fireplace

YES NO

3) Floors (circle all that apply)

Hardwood Carpet Ceramic Tile Vinyl Tile

Unfinished Wood Unfinished Concrete Other stained concrete

4) Walls (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

5) Ceiling (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

(b)(6) **eatures**

Exterior

Extensive Landscaping including 7 live oak trees
12 Zone Irrigation System
Custom exterior lighting
1,500 gallon heated Swim Spa
Outdoor cooking area with 36" BBQ, refrigerator and sink
TV on spa level included
St. Louis used brick and "Old World" stucco finish
Operable Spanish Cedar Shutters
Copper Gutters with subsurface drainage
Upper and Lower, front & rear covered porches
Circular drive with abundant off street parking
Custom Iron Railings
Ridge Tiles
1.2 Acre Home site

Miscellaneous

15 KW (b)(3):C natural gas generator with manual transfer
Closed cell foam "envelope system" insulation
3 high efficiency, 2 speed A/C systems w/gas heat (b)
1st Floor & Garage has high efficiency heat pump system
Abundant insulated attic space
3 story elevator
Central Vacuum System w/ floor outlet in kitchen
Completed October 2005
Custom 8 ft. beveled front door and sidelights
Gas Lighting on front porch and spa deck
Ceiling fans on rear balcony & spa deck
(b)(3):CPS Custom Audio/Video system throughout the house

Garage

Air conditioned
Parking for 7 cars
9' 6"' Overhead clearance for boat or trailer parking
Work bench with cabinets and sink
4' vinyl wainscot
Painted floor
Insulated (b) (3):CPSA oors with remote control operators
Ceiling recessed stereo speakers

1st Floor

Scored & Stained concrete floors
Beaded board wainscot
Game room
Bath with shower, Studio/Bedroom
Laundry Room with cabinets and sink & W/D Hook ups
Storage room which can be converted to a BR and Bath (Doors to garage and side driveway)
Ceiling recessed stereo speakers

2nd Floor (Main Living Area)

Hard wood floors on main living area (Caribbean Pine with Ebony finish)
Custom Millwork
12 foot Ceilings
Ceiling recessed stereo speakers
Fireplace (wood burning or gas) with custom limestone mantle and hearth
Custom recessed lighting throughout

Study

Built in his & her desks and bookcases
Closet with custom shelving
Ceiling recessed stereo speakers

Powder Room

Faux painted walls
Custom made sink cabinet

Island Kitchen

Custom Faux Painted Walls
Granite countertops w/ tumbled stone back splash
Custom Cabinets and Hood
Above, under, and inside cabinet lighting
(b)(3):CPS built in side by side refrigerator (included)
(b)(3): CP 48" Gas Range w/ dbl ovens, 6 burners, & griddle
Vent a Hood with double Blower
Double stainless sink and prep sink, each w/ garbage disposals
(b)(3):CPSA Section 6(b) dishwasher
Double Refrigerator Drawers
Built in Microwave
GE Profile Trash Compactor
Ceiling recessed stereo speakers

Pantry

Pantry w/ custom cabinets & shelves
Granite countertop
(b)(3):CPSA S asher & dryer (included)

Den (Keeping Room)

Custom Built in corner TV unit in Den
Wired for Cable, Satellite and Surround system
Ceiling recessed stereo speakers
55" flat screen TV and satellite video recorder with surround sound
(audio & video equipment is included)

Bar

Granite counter top
Custom cabinets w/glass fronts
TV niche above closet (TV not included)
Above, below, & inside lighting
Stainless sink
Pantry with shelving
(b)(3):CPSA Section 6(b) Wine Center
Beverage Center
Ice Maker
Custom Faux Painted Walls
Ceiling recessed stereo speakers

Master Bedroom & Bath

Entrance Foyer and Separate Sitting area
Access to rear balcony & spa deck
Custom Built in TV Cabinet (equipment not included)
Wired for surround sound system w/ceiling speakers
Recessed directional lighting for reading
Custom Built in Bookshelves and Cabinets
Limestone fireplace front in Bedroom
Double sided Gas Fireplace (Viewed in BR & Bath)
Marble countertops, tub deck, & fireplace front
Custom Cabinets & Drawers
Limestone walls & floors
Separate toilet with limestone wainscot & chair rail
Custom Limestone & Marble Shower
Delta 3 zone shower system with body massage, and hand held
Plumbing for steam shower system
Toe heaters below each sink area
TV mounted on wall (included)
Custom Arched Mirrors
Double sinks with separate vanity area
Corner (b)(3): Tub with built in heating unit
Custom his & her closet
14' Built in Cabinet, shelves & drawers
Under cabinet lighting
Phone connections in closet & toilet areas
Electrical outlets in cabinets

3rd Floor

Rear bedroom with double dormer
Two front bedrooms with single dormers
Jack and Jill Bath connecting both bedrooms (Each with own vanities)
Breccia tile vanity tops
Tile floors in baths
Cultured marble tub walls
Ceiling fans in BR's with lighting and remote controls
Girl's bedroom & bath with custom faux painted walls
Breccia tile counter & vanity tops in girl's bath
Custom closet shelving in all bedrooms
Wood floors in 3rd floor hallway
Carpet in all 3rd floor bedrooms



1st Floor Living Area & Garage



Main Level (2nd Floor)



Third Floor

Main Level (2nd Floor)	3,826
3rd Floor	1,489
2nd & 3rd Floor Living Area	5,315
1st Floor Living Area (Below BFE)	1,943
Total Living Area	7,258
Garage	1,778
Porches	958
Spa Deck	445
Total Under Beam	10,439

ACTIVE SAM E FIELD DATA

Page __ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/21

Project#: _____

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	Vol (L)	NOTES
102085	2	Great Room	Organic	S	10146	.49		.52	12:28	201	102	
102086	2	Great Room	Organic	D	07766	.50		.54	12:28	201	95	
102087	2	Master BR	Organic		12989	.50		.53	12:32	202	104	
102088	3	BR #2 #3	Organic		13501	.49		.50	12:35	207	102	
102089	2	Outdoor	Organic		13009	.50		.46	12:30	202	97	
102090	-	MB	Organic		-	-		-	-	-	0	
102091	2	Great Room	Inorganic	S	13445	.49		.51	12:28	201	101	
102092	2	Great Room	Inorganic	D	10483	.50		.50	12:28	201	101	
102093	2	Master BR	Inorganic		13858	.49		.51	12:32	202	101	
102094	3	BR #2 #3	Inorganic		10486	.50		.52	12:35	207	106	
102095	2	Outdoor	Inorganic		02978	.50		.48	12:30	202	99	
102096	-	MB	Inorganic		-	-		-	-	-	0	
1	2	Great Room	Aldehyde	S	06759	.51		.51	12:28	201	103	
2	2	Great Room	Aldehyde	D	02994	.49		.51	12:28	201	101	
3	2	Master BR	Aldehyde		13481	.51		.46	12:32	202	98	
4	3	BR #2 #3	Aldehyde		02711	.50		.50	12:35	207	104	
5	2	Outdoor	Aldehyde		13459	.51		.47	12:30	202	100	
6	-	MB	Aldehyde		-	-		-	-	-	0	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

~~VOC~~ SAMPI ~~FIELD~~ DATA

Sulfur Grab Bags

Page __ f ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/21/09

Home Address: (b)(6) , LA

Project#: 16512

Field Person(s): MAF

SAMPLE ID	CANISTER ID	FLOW CONTROL ID	GAUGE ID	FLOOR	LOCATION	SAMPLE TYPE	GAUGE PRESSURE START	START TIME	GUAGE PRESSURE END	END TIME	NOTES
B1					Great Room	S					
B2					Great Room	D					
B3					Master BR	S					
B4					BR #3	S					
B5					Outdoor Air	S					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/21

Project#: _____

XRF Serial #: 10452

XRF Scan Time 20 sec

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
2	3	BR #3	S	6'	wall	1			9:29	104	
3	3	"	E	6'	wall	2			9:30	176	
4	3	"	N	2'	wall	3			9:30	417	
5	3	"	E	6'	wall	4			9:31	121	
6	3	"	W	2'	wall	5			9:31	342	
7	3	"	N	6'	wall	6			9:32	363	
8	3	"	W	2'	wall	7			9:32	365	
9	3	"	W	6'	wall	8			9:33	354	
10	3	"	E	2'	wall	9			9:34	126	
11	"	"	W	6'	wall	10			9:35	220	
12	"	"	E	2'	wall	11			9:36	173	
13	"	"	N	6'	wall	12			9:37	404	
14	"	"	S	6'	wall	13			9:38	436	
15	"	BR #2	E	6'	wall	14			9:39	117	
16	"	"	E	2'	wall	15			9:40	154	
17	"	"	W	6'	wall	16			9:41	121	
18	"	"	N	2'	wall	17			9:41	165	
19	"	"	W	6'	wall	18			9:42	113	
20	"	"	S	18"	wall	19			9:42	~~114~~ 140	outlet

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: _____
Project#: _____

XRF Serial #: _____
XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
21	3	BR #2	S	6'	wall	20			9:44	126	
22	"	"	E	6'	"	21			9:44	N/D	
23	"	"	W	6'	"	22			9:45	N/D	
24	"	"	S	6'	"	23			9:46	N/D	
25	"	"	E	6'	"	24			9:47	N/D	
26	"	"	N	2'	"	25			9:47	N/D	
27	"	BR #4	N	~~2'~~ 6	"	26			9:49	N/D	
28	"	"	W	2'	"	27			9:49	N/D	
29	"	"	W	6'	"	28			9:50	N/D	
30	"	"	E	~~6'~~ 18"	"	29			9:51	N/D	outlet
31	"	"	E	6'	"	30			9:52	N/D	
32	"	"	W	6'	"	31			9:53	N/D	
33	"	"	E	2'	"	32			9:53	N/D	
34	"	Attic	E	6'	"	33			9:54	N/D	
35	"	Hall	N	6'	"	34			9:54	N/D	
36	"	Hall	S	18"	"	35			9:55	N/D	outlet
37	"	Hall	S	18"	"	36			9:57	N/D	Duplicate
38	"	BR #3	S	6'	"	37			9:57	N/D	
39	"	"	S	6'	"	38			9:58	N/D	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/21

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
40	2	Foyer	N	18"	~~B~~ wall	39			10:03	N/D	outlet
43	3	Hall	N	6'	wall	40			10:03	169	
44	3	Hall	W	6'	wall	41			10:04	124	
45	"	"	W	6'	"	42			10:05	139	Duplicate
46	"	"	E	6'	"	43			10:09	159	
47	"	"	W	6'	"	44			10:10	142	
48	"	"	N	~~6"~~ 6'	"	45			10:11	205	
49	2	"	S	6'	"	46			10:11	277	
50	2	Study	S	6'	"	47			10:13	285	
51	"	"	E	2'	"	48			10:14	153	
52	"	"	N	6'	"	49			10:14	293	
53	"	"	W	18"	"	50			10:15	150	outlet
54	"	"	S	6'	"	51			10:16	182	
55	"	Bath #2	E	6'	"	52			10:17	292	
56	"	"	N	2'	"	53			10:17	282	
57	"	"	S	6'	"	54			10:18	334	
58	"	Closet	S	6'	"	55			10:19	217	
59	"	~~C~~ Foyer	N	18"	"	56			10:20	240	outlet
60	"	Foyer	N	6'	"	57			10:20	149	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/21

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
61	2	Bar	E	4'	Wall	58			10:22	116	
62	"	Bar	E	4'	"	59			10:23	118	Duplicate
63	"	"	N	~~2~~ 6'	"	60			10:24	143	
64	"	"	W	2'	"	61			10:25	184	
65	"	"	S	6'	"	62			10:25	164	
66	"	Great Room	W	2'	"	63			10:26	295	
67	"	"	S	6'	"	64			10:26	211	
68	"	Master BR	SE	6'	"	65			10:28	288	
69	"	"	W	2'	"	66			10:28	249	
70	"	"	W	2'	"	67			10:29	261	Duplicate
71	"	"	E	6'	"	68			10:30	297	
72	"	"	N	6'	"	69			10:30	384	
73	"	"	E	6'	"	70			10:32	127	
74	"	"	N	2'	"	71			10:32	249	
75	"	"	W	6'	"	72			10:33	294	
76	"	"	NW	~~4~~ 6'	"	73			10:33	280	
77	"	"	N	2'	"	74			10:34	243	
78	"	"	W	6'	"	75			10:34	200	
79	"	"	S	2'	"	76			10:35	216	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6) Lawrenceville, LA

Field Person(s): _____

Date: 8/21

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
80	2	Master BR	S	2'	wall	77			10:35	207	
81	"	"	W	6'	"	78			10:36	224	
82	"	"	NE	6'	"	79			10:36	257	
83	"	"	E	2'	"	80			10:38	285	
84	"	Great Room	W	18"	"	81			10:39	145	outlet
85	"	"	W	6'	"	82			10:39	211	
86	"	"	S	18"	"	83			10:41	171	outlet
87	"	"	E	18"	"	84			10:41	136	
88	"	Den	W	6'	"	85			10:42	245	
89	"	"	W	6'	"	86			10:42	251	Duplicate
90	"	"	S	6'	"	87			10:43	251	
91	"	"	E	18"	"	88			10:44	139	Outlet
92	"	"	N	6'	"	89			10:45	248	
93	"	Kitchen	W	6'	"	90			10:46	236	
94	"	"	W	6'	"	91			10:46	201	Duplicate
95	"	"	W	2'	"	92			10:47	265	
96	"	"	N	~~6'~~ 2' 18"	"	93			10:48	103	
97	"	"	W	6'	"	94			10:49	280	
98	2	"	E	6'	"	95			10:52	295	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page ___ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ (b)(6) _____

Home Address: _____ Vanderville, LA

Field Person(s): _____

Date: 8/21

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
99	1	Stairwell	E	6'	wall	96			10:55	258	
100	"		S	6'	"	97			10:56	212	
101	"	Foyer	S	6'	"	98			10:56	268	
102	"	Foyer	S	6'	"	99			10:57	266	Duplicate
103	"	Studio	S	6'	"	100			10:58	225	
104	"	Studio	E	6'	"	101			10:58	227	
105	"	"	N	6'	"	102			10:59	224	
106	"	"	W	6'	"	103			10:59	288	
107	"	Laundry	W	6'	"	104			11:01	255	
108	"	"	E	6'	"	105			11:02	266	
109	"	Bath	E	6'	"	106			11:03	242	
110	"	"	W	6'	"	107			11:04	245	
111	"	Foyer	W	6'	"	108			11:05	282	
112	"	Game Room	N	6'	"	109			11:06	250	
113	"	"	N	4'	"	110			11:07	271	outlet
114	"	"	W	6'	"	111			11:08	277	
115	"	"	S	4'	"	112			11:08	272	
116	"	Storage	E	6'	"	113			11:09	258	
117	"	"	S	6'	"	114			11:09	239	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

*C = Ceiling

Client: _____

Home Address: (b)(6) [redacted], Mandeville, LA

Field Person(s): _____

Date: 8/21

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
118	1	Garage	S	6'	wall	115			11:10	167	
119	"	"	S	6'	"	116			11:10	148	Duplicate
120	"	"	N	6'	"	117			11:11	345	
121	"	"	SW	6'	"	118			11:12	122	
122	"	"	S	6'	"	119			11:13	160	
123	"	"	N	6'	"	120			11:14	189	
124	"	"	N	6'	"	121			11:15	202	
125	"	"	S	6'	"	122			11:16	156	
129	3	~~Hallway~~ BR #3	C*	C	C	123			2:14	373	
130	"	"	C	C	C	124			2:15	345	
131	"	BR #2	C	C	C	125			2:16	243	
132	"	"	C	C	C	126			2:17	229	Duplicate
133	"	BR #4	C	C	C	127			2:19	356	
134	"	"	C	C	C	128			2:20	134	
135	"	Hallway	C	C	C	129			2:22	141	
136	"	Hallway	C	C	C	130			2:23	133	
137	1	Studio	C	C	C	131			2:27	119	
138	"	Laundry	C	C	C	132			2:34	238	
139	1	Bath	C	C	C	133			2:36	250	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAI IELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

*C = Ceiling

Client: _____ (b)(6) _____

Home Address: _____ Mandeville, LA

Field Person(s): _____

Date: 8/21
Project#: _____

XRF Serial #: _____
XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
140	1	Bath	C*	C	C	134			2:38	222	Duplicate
141	"	Game Room	C	C	C	135			2:40	264	
142	"	Storage	C	C	C	136			2:42	321	
143	"	~~Foyer~~ Garage	C	C	C	137			2:44	100	
144	"	Garage	C	C	C	138			2:46	116	
145	"	Garage	C	C	C	139			2:47	125	
146	"	"	C	C	C	140			2:47	122	
147	"	Hallway	C	C	C	141			2:48	~~289~~	289
148	2	Great Room	C	C	C	142			2:55	291	
149	"	Study	C	C	C	143			2:58	~~149~~	253
150	"	Bath 2	C	C	C	144			3:00	277	
151	"	Great Room	C	C	C	145			3:01	221	
152	"	Great Room	C	C	C	146			3:04	128	
153	"	Master BR	C	C	C	147			3:06	239	
154	"	Master BR	C	C	C	148			3:08	221	
155	"	Master BR	C	C	C	149			3:09	223	Duplicate
156 ~~156~~	"	Master BR	C	C	C	150			3:13	290	
157	"	Master BR	C	C	C	151			3:14	205	
158	"	"	C	C	C	152			3:16	251	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

* C = Ceiling

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/21

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
159	2	Den	C*	C	C	153			3:22	248	
160	"	"	"	"	"	154			3:22	274	Duplicate
161	"	Kitchen	"	"	"	155			3:24	108	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

VISUAL CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: (b)(6)

Date: 8/21

Home Address: Mandeville, LA

Project#:

Field Person(s):

* Duplicate: FTIR21/105161

LOCATION ID	FLOOR	LOCATION	WALL COOR.	Bulk SAMPLE ~~LOCATION~~ I.D.	CORROSION RATING	Photo #	NOTES
1A	2	Living Room/Great Room	E	FTIR 11 105140	1	217	
2A		Master Bedroom	S	FTIR 12/105141	1	218	
3A		Great Room	N	FTIR 10/105142	1	219/220	Marked Foyer on Map
4A		Great Room	N	FTIR 9/105143	1	321	
5A		Study	E	105144 FTIR 7/105145 FTIR8	1	222/223	Dup.
6A		TV Room	S	FTIR 13/105146	1	224	
7A		Kitchen	W	FTIR 14/105147	1	225	
8A	3	Bedroom #3	E	FTIR 1/105148	1	226	
9A		Bedroom #2	N	FTIR 6/105149	1	227	
10A		Bath 5	S	FTIR 4/105150	1	228	
11A		Bedroom #4	N	FTIR 3/105151	1	229	
12A		Hallway	W	FTIR 2/105152	1	230	
13A		Bedroom #2	N	FTIR 5/105153	1	231/232	
14A	1	Bedroom #5/Study	W	FTIR 16/105154	1	233	
15A		Lower Foyer	W	FTIR 15/105155	1	234/235	
16A		Game Room	S	FTIR ~~16~~ 20* 105156	1	236	
17A		Game Room	E	FTIR 19/105157	1	237-239	
18A		Bedroom #5/Study	E	FTIR 17/105158	1	240/241	
19A		Laundry Room	E	FTIR 18/105159	1	242	
20A		Garage	N	~~FTIR 16~~ FTIR22 105160	1	243	
21A		BR #2	S	8"x8"	—	—	

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

~~ACTIVE SAM~~ E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Hobo

Client: _____

Date: _____

Project#: _____

Home Address: _____

ROTA ID #: _____

Field Person(s): _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
#2415760	2	Master Bedroom	Temp/RH								
2415758	2	Great Room									
2415759	3	Bedroom #2									

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

~~ACTIVE~~ SAMPLE FIELD DATA

Page __ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

QTrak

Client: _____

Home Address: (b)(6) Mandeville, LA

Field Person(s): _____

Date: 8/21

Project#: _____

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
30045	2	Great Room									
30120	3	Bedroom #2									
30058	2	Master Bedroom									

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

062109LA01

967

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date:

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ 106704		LIVING ROOM	H_2S	S	9/8/09	12:30	9/21/09	1:05 PM	
✓ 106705		DUPLICATE	↓	D	↓	↓	↓	↓	
✓ 106706		OUTDOORS	↓	S	↓	↓	↓	↓	
✓ 106707		GUEST	↓	S	↓	↓	↓	↓	
✓ 106708		MASTER	↓	S	↓	↓	↓	↓	
✓ 106709		—	—	FB	—	—	—	—	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

PASSIVE SAMPLE FIELD DATA

968

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date:

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ 106710		LIVING ROOM	ALDEHYDE	S	9/8/09	12:30	9/21/09	1:05 PM	
✓ 106711		DUPLICATE	↓	D	↓	↓	↓	↓	
✓ 106712		OUTDOORS	↓	S	↓	↓	↓	↓	
✓ 106713		GUEST	↓	S	↓	↓	↓	↓	
✓ 106714		MASTER	↓	S	↓	↓	↓	↓	
✓ 106715	—	—	—	FB	—	—	—	—	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

969

Client: CPSC

Home Address: (b)(6)

Field Person(s): TMM

Date:

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
106716		LIVING ROOM	NO_2 SO_2 HF	S	9/8/09	12:30	9/21/09	1:05 PM	
106717		DUPLICATE		D					
106718		OUTDOORS		S					
106719		GUEST		S					
106720		MASTER		S					
106721				FB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

0821091A01

970

Client: CPSC

Home Address (b)(6)

Field Person(s): TMM

Date:

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ 106722		LIVING ROOM	OZONE	S	9/8/09	12:30	9/21/09	1:05 pm	
✓ 106723		DUPLICATE		D					
✓ 106724		OUTDOORS		S					
✓ 106725		GUEST		S					
✓ 106726		MASTER		S					
✓ 106727				FB					
		HOBOS ON @ 12:30	ON 9/8/09		end @	1:05 pm	on 9/21/09		
	✓	2415758 - LIVING							
	✓	2415759 - GUEST							
	✓	2415760 - MASTER							

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Page ___ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

971

Client: CPSC

Home Address: (b)(6)

Field Person(s): THM

Date:

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
106728		LIVING ROOM	COUPON	S	9/8/09	12:30	9/21/09	1:05 PM	63375
106729		OUTDOOR							63374
106730		GUEST							63385
106731		MASTER							63382
106732		SUPPLY							63379

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: (b)(6)

Home Address: Mandeville, LA

Date: 8/27

Project#:

Field Person(s):

Camera ID:

PHOTO NO.	FLOOR	LOCATION	NOTES
195	3	Hot Water Heater ID	#2
196	3	Hot Water Heater	#2
197	3	Hot Water Heater ID	#3
198	3	Hot Water Heater [redacted]	#3
199	3	Sink Pipes (Bedroom #2)	
200	outdoors	Compressor Details	
201	"	"	
202	3	Air Handler Product Info (b)(3):CPSA Section 6(b)	#1
203	3	Coils (Carrier [redacted])	
204	3	"	
205	3	"	
206	3	Air Handler Product Info	#2
207	"	Copper Line	
208	"	Coils	
209	"		
210	"		
211	"		
212	"	Dry Wall Product Info	
213	"	Copper Water Piping	
214	"	"	
215	"	Copper Piping above Water Heater	
216	"	"	

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ Date: 8/21

Home Address: (b)(6) Vanderville, LA Project#: _____

Field Person(s): _____ Camera ID: _____

PHOTO NO.	FLOOR	LOCATION	NOTES
166	outside	House Front	
167		House Side/Garage	
168		House Back	
169		House Side	
170		Compressor #1 ID	
171		Compressor #2 ID	Badly Faded
172		"	Badly Faded
173		Compressor #3 ID	
174		Compressor #3 ID	Bad Picture
176		"	
177		Compressor #4 ID	
178		"	
179		Visible Corrosion on lines	
180		Compressor Units	
181		"	
182	1	Pipes Behind Sink 1st floor Bathroom	
183	1	Pipes Behind Sink (Laundry Room)	
184	2	Sink Pipes (Kitchen)	Sink #1
185	2	Sink Pipes (Kitchen)	"
186		Sink Pipes (Kitchen)	Sink #2
187		Copper Cups	"
188		Sink Pipes (Bar)	
189		Sink Pipes ~~Bathroom~~ (Master Bath)	
190		"	
191	~~3~~ 2	~~Hot Water Heater ID~~ Sink Pipes Master Bath	
192	3	Hot Water Heater ID	#1
193	3	Hot Water Heater	#1
194	3	Hot Water Heater	#1