ENVIRONMENTAL HEALTH & ENGINEERING

Environmental Health & Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

House ID 090209VA01

Date 9/2/09

Field Technician(s) MAE John Tuco (b)(6)

House Address (b)(6) rfolk VA

General Weather Description Sunny 70°F

1. Questionnaire

1) Interviewed home owner (YES) NO

2) Age of the House (years)

built 2005

3) Estimated Floor Area (sqft)

2500

4) Was as there any demo's to the house?

YES (NO)

If YES, when was it done? Please Explain.

5) Has there been any fire in the building?

YES (NO)

If YES, when did it happen? Please Explain.

6) Any pesticides/herbicides been applied around the building or in the yard?

(YES) NO

If YES, when was it applied? Please list the type of chemicals used.

Base of garage last oct

7) Has there been any recent painting/staining done in the home?

YES NO

If YES, when, where and what type of paint/stain was used?

8) Has any work been done on the AC system since construction?

YES NO

If YES, please describe?

Coils replaced ~~by~~ prior to moving in Oct 2008

9) Are all the AC system components original?

YES NO

If NO, please describe?

New coils

10) What is the age of your refrigerator?

Not new w/ townhouse years purchased used from friend

11) Has any piping been replaced in the home?

YES NO

If YES, please describe?

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many units?

Multi family town house building

2) Number of rooms

3 br 3.5 bath 6

3) Above grade Construction

Wood Frame Concrete Stone Brick Other _____

4) Basement

Full Crawlspace Slab Other _____

5) Foundation

Concrete Cinder Block Stone Other_____

6) Garage

YES NO

If YES, Attached Detached

If YES, Used for Car Parking? YES NO

If YES, Any gas-powered equipment or cans of gasoline/fuels stored?

YES NO

7) Type of HVAC System

_____

Make _____ HVAC Model _____ Condenser Model _____

8) Types of Fuel (circle all that apply)

Natural Gas Fuel Oil Kerosene Electric

Propane Solar Wood Coal

9) Water Supply

Public Well Other _____

10) Sewage

Public Septic Leach Field Other _____

11) Attic

Finished Unfinished

3. Interior Characteristics

1) Any odors upon entering the building?

YES NO

If YES, describe burnt match but stronger

2) Fireplace

YES NO

3) Floors (circle all that apply)

Hardwood Carpet Ceramic Tile Vinyl Tile

Unfinished Wood Unfinished Concrete Other _____

4) Walls (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

5) Ceiling (circle all that apply)

Wall Paper Paint Skim Coat Textured

Wood or Wood Paneling Other _____

1st Floor

N
S

Closet #2
width: 5'00"
Length: 4'7"
Height: 8'4"

Machine Room
Length: 6'
width: 4'11"
Height 1: 8'4"
Height 2: 6'9"

Closet #1
Length: 6'03"
Width: 2'06"
Height: 8'4"



Dimensions:

Guest BR:
Length: 12'06"
Width:

Guest Closet:
width: 5'06"

Hallway:
Length: 17'0"
width: 3'06"
Height: 8'03"

Entrance Vlay
Length: 9'03"
Vlidth: 8'03"

Garage:
width: 11'06"
Length 24'02"
Height: 9'0"

Page 1

House Address (b)(6)

6/2/04

House Address (b)(6)

Page 2

9/2/09

2nd Floor Living Room + Kitchen



Master Bedroom 3rd Floor

House Address (b)(6)

Page 4



3rd Floor
Bedroom

House Address (b)(6)

Page 3



VOC SAMPI FIELD DATA

Page __ f ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ (b)(6)

Home Address

Date: 9/2

Project#: _____

Field Person(s): _____

SAMPLE ID	CANISTER ID	FLOW CONTROL ID	GAUGE ID	FLOOR	LOCATION	SAMPLE TYPE	GAUGE PRESSURE START	START TIME	GUAGE PRESSURE END	END TIME	NOTES
104895	1636	—	—	—	MB	—	—	—	—	—	
104896	1668	649	157	2	Living Room	S		9:30			
104897	1662	605	881	2	Living Room	D		↓			
104898	568	415	990	3	Master BR	S					
104899	1498	516	1125	1	Guest BR	S					
104900	1244	583	1096	2	Outdoor	S					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM[illegible]E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6)

Field Person(s): _____

Date: 9/2

Project#: _____

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
104869		FB	Aldehyde	—	—	—	—	—	—	—	
104870		Living Room		S	06737	.49		.52	12:45	202	
104871		"		D	G17	.51 ~~.49~~		.49	12:45	202	
104872		Master BR		S	G15	.51		.49	12:49	209	
104873 ~~104878~~		Guest BR		S	G14	.49		.48	12:51	210	
104874		Outdoor		S	G05	.49		.46	12:47	210	
104889 ~~104875~~		FB	Organic	—	—	—	—	—	—	—	
104890 ~~104876~~		Living Room			13459	.51		.49	12:45	202	
104891 ~~104877~~		"			G13	.49		.46	12:45	202	
104892		Master BR			12989	.49		.50	12:49	209	
104893		Guest BR			10142	.50		.51	12:51	210	
104894		Outdoor			~~10~~ 13858	.50		.52	12:47	210	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM..LE FIELD DATA

Page _ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6)

Field Person(s): _____

Date: 9/2

Project#: _____

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
104875		Living Room Front	Inorganic	S	13009	.51		.46	3:58	393	~~+202 min.~~ ~~+163~~ +28
104876		Living Room Back		S	13009	.51		.46	3:58	393	
104877		Living Room Front		D	13481	.50		.49	3:58	395	
104878		Living Room Back		D	13481	.50		.49	3:58	395	
104879		Master BR Front		S	02994	.50		.47	3:25	359	
104880		Master BR Back			02994	.50		.47	3:25	359	
104881		Guest BR Front			13445	.51		.48	3:58	397	
104882		Guest BR Back			13445	.51		.48	3:58	397	
104883		Living Room		S	07766	.51		.50	12:45	202	
104884		"		D	P02	.49		.43	12:45	202	
104885		Master BR		S	G08	.49		.46	12:49	209	
104886		Guest BR			10483	.51		.47	12:51	210	
104887		Outdoor			02776	.49		.49	12:47	210	
104888		FB	Inorganic		—	—	—	—	—	—	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Grab Bags

Page _ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6)

Field Person(s): _____

Date: 9/2

Project#: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
104954	2	Living Room	Sulfur	S					
104955	2	"		D					
104956	2	Outdoor		S					
104957	1	Guest BR		S					
104958	3	Master BR		S					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCA FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ (b)(6)

Home Address: _____

Field Person(s): _____

Date: 9/2
Project#: 1

XRF Serial #: 10452
XRF Scan Time 30 sec

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
4	1	Guest BR	S	6'	wall				10:47	2428	
5			E	6'					10:48	2216	
6			N	2'					10:49	2169	
7			W	6'					10:50	1737	
8			S	6'					10:50	1536	
9			S	18"					10:51	1722	outlet
10			W	6'					10:51	1721	
11			W	2'					10:52	1378	
12			W	2'					10:52	1283	Duplicate
13			N	6'					10:53	1742	
14			N	4'					10:54	1281	
15			E	18"					10:54	1107	outlet
16			W	6'					10:55	1921	
17			S	6'					10:56	1849	
18			E	6'					10:57	979	
19			N	4'					10:58	649	
20		1st Hall	W	18"					10:58	1953	outlet
21			S	6'					10:59	1359	
22			S	2'					11:00	1521	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCA. FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ (b)(6)

Home Address: _____

Field Person(s): _____

Date: 9/2

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
23	1	1st Hall	S	2'	wall				11:00	1603	Duplicate
24			E	4'					11:01	627	Light Switch
25			N	2'					11:02	393	
26			N	6'					11:02	435	
27			N	2'					11:03	1779	
28			S	6'					11:07	1276	
29			S	2'					11:07	1861	
30			S	2'					11:08	1692	Duplicate
31			E	6'					11:08	1632	
32			W	6'					11:09	1804	
33			E	6'					11:10	2707	
34			N	6'					11:10	1759	
35			W	6'					11:11	447	
36		Garage	S	6'					11:12	385	
37			S	5'					11:13	410	
38			N	6'					11:13	424	
39			N	2'					11:14	386	
40			E	6'					11:15	400	
41		1st Hall	N	6'					11:16	345	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCA. FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6)

Field Person(s): _____

Date: 9/2
Project#: _____

XRF Serial #: _____
XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
42	1	1st Hall	S	6'	Wall				11:17	426	
43	2	Living Room	W	6'					11:19	331	
44		Kitchen	E	4'					11:20	455	
45			W	5'					11:20	421	
46			N	18"					11:21	344	outlet
47			W	5'					11:21	487	
48			W	5'					11:22	466	Duplicate
49			E	6'					11:22	466	
50			N	5'					11:23	524	
51			N	6'					11:24	404	
52			W	2'					11:24	384	
53			S	4'					11:25	336	Light Switch
54			E	6'					11:26	359	
55			NW	2'					11:26	455	
56			SW	6'					11:27	342	
57			S	5'					11:28	366	
58			S	4'					11:28	387	outlet
59			S	4'					11:29	392	outlet (duplicate)
60		Living Room	S	6'					11:30	433	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCA. FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____

Home Address: (b)(6)

Field Person(s): _____

Date: 9/2

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
61	2	Living Room	S	18"	Wall				11:31	380	outlet
62			S	6'					11:31	325	
63			S	2'					11:32	378	
64			E	18"					11:32	444	outlet
65			N	18"					11:33	455	outlet
66			N	6'					11:34	480	
67			E	4'					11:35	1446	Light Switch
68			N	6'					11:35	407	
69			S	11'					11:36	1564	
70			N	6'					11:37	812	
71	3	Master BR	S	18"					11:39	1795	outlet
72			S	18"					11:39	1827	duplicate outlet
73			N	6'					11:40	1570	
74			N	6'					11:40	621	
75			N	18"					11:41	1395	outlet
76			E	18"					11:42	1597	outlet
77			E	18"					11:42	1619	outlet duplicate
78			E	18"					11:43	1765	outlet
79			S	6'					11:44	1479	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCA. FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ (b)(6)

Home Address: _____

Field Person(s): _____

Date: 9/2

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
80	3	Master BR	S	6'	wall				11:44	750	
81		"	W	6'					11:45	1491	
82			W	2'					11:45	1635	
83			E	4'					11:46	454	Light Switch
84			N	6'					11:46	1642	
85			E	2'					11:47	1787	
86			S	~~6'~~ 5'					11:47	1632	
87			W	6'					11:48	1458	
88			E	4'					11:48	638	Outlet
89			W	6'					11:49	2323	
90			E	6'					11:50	448	
91			E	6'					11:50	456	
92			W	6'					11:50	2310	
93			S	5'					11:51	2139	
94			S	6'					11:52	2232	
95			W	2'					11:52	2220	
96			E	6'					11:53	2207	
97		3rd Hall	S	18"					11:54	1742	outlet
98		"	S	18"					11:54	1675	outlet duplicate

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCA. FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ (b)(6)

Home Address: _

Field Person(s): _____

Date: 9/2

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
99	3	3rd Hall	E	4'	wall				11:55	464	Light Switch
100		"	N	6'					11:56	1441	
101		"	W	6'					11:56	688	
102		Bedroom #1	E	18"					11:59	2105	outlet
103			E	18"					11:59	2134	outlet duplicate
104			E	6'					12:00	1530	
105			N	6'					12:00	1540	
106			S	5'					12:02	1752	
107			E	6'					12:02	1401	
108			S	6'					12:03	1963	
109			S	2'					12:04	1543	
110			S	2'					12:05	1608	Duplicate
111			W	6'					12:05	1214	
112			W	18"					12:06	1438	outlet
113			N	6'					12:06	1737	
114			~~WS~~	18"					12:07	1029	outlet
115			W	18"					12:08	1004	outlet duplicate
116			S	4'					12:08	829	Light Switch
117			S	2'					12:09	1377	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCA. FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

&C = Ceiling

Date: 8/9/2
Project#:

Client:

Home Address: (b)(6)

XRF Serial #:
XRF Scan Time

Field Person(s):

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
118	3	Bedroom #1	NE		wall				12:11	1207	
119			N						12:12	1898	
120			E						12:13	1483	
121		Master BR	&C	C	C				12:15	1777	
122		"							12:16	644	
123		"							12:17	1703	
124		"							12:20	1733	
125		"							12:21	1589	
126		3rd Hall							12:22	520	
127		BR #1							12:23	1876	
128		"							12:23	1786	Duplicate
129		"							12:24	1445	
1 130		"							12:25	1481	
131	2	Living Room							12:35	1084	
132		"							12:37	1641	
133		Kitchen							12:38	541	
134									12:39	1196	
135									12:40	2009	
136									12:41	1703	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCA FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ (b)(6)

Home Address: _____

Field Person(s): _____

*C = Ceiling

Date: 1/2

Project#: _____

XRF Serial #: _____

XRF Scan Time _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
137	2	Kitchen	C*	C	C				2:04	1571	
138	1	1st Hall							2:06	1524	
139		"							2:07	1870	
140		"							2:07	1846	Duplicate
141		Garage							2:09	435	
142		"							2:10	476	
143		Guest BR							2:12	1402	
144		"							2:13	1876	
145		"							2:14	480	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

VISUAL CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

ient: _____ (b)(6)

Home Address: _____

Field Person(s): _____

Date: 9/2/09

Project#: 16512

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES Photo
A	2	Bathroom	S	switch	3	1549-1551
B	2	Kitchen	NW	outlet	3	1552-1554
C	2	Kitchen	N	outlet	3	1555-1558
D	2	Laundry Room	W	switch	2	1559-1561
E	2	Living Room	S	outlet	3	1562-1565
F	2	Living Room	N	outlet	3	1562-1566
G	3	Master Bedroom	NE	outlet	3	1567-1569
H	3	Master Bedroom	SE	outlet	3	1570-1572
I	3	Master Bedroom Hallway	S	outlet	3	1573-1574
J	3	Master Bathroom	E	switch	3	1574-1578
K	3	Master Bath/closet Entrance	E	switch	3	1579-1581
L	3	3rd Floor Hallway	S	outlet	3	1582-1583
M	3	3rd Floor Hallway Closet	E	switch	3	1584-1587
N	3	3rd Floor Bathroom	S	switch	3	1588-1589
O	3	3rd Floor Bedroom	W	outlet	3	1590-1593
P	3	3rd Floor Bedroom	E	outlet	3	1594-1595
Q	1	Entrance Way	W	outlet	3	1596-1597
R	1	1st Floor Guest Bedroom	W	switch	3	1598-1601
S	1	1st Floor Guest Bedroom	W	outlet	3	1602-1604
T	1	1st Floor Hallway	S	switch	3	1605-1606
U	1	Garage	N	switch	1	1607-1608

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

BULK SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 9/2/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): MAF, Juan, John

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	LOCATION ID (SAME AS XRF LOG)	NOTES
104901	2	Kitchen	N	C 46	~~outlet~~
104902	2	Kitchen	W	B 55	~~outlet~~
104903	2	Bathroom	S	A 52	
104904	2	Laundry Room	W	D 47	
104905	2	Laundry Room	W	D 47 Dup	
104906	2	Living Room	S	E 60	
104907	2	Living Room	N	F 65	
104908	1	Front Hall	W	Q 20	
104909	1	Front Hall	S	T ~~2T~~ 21	
104910	1	Guest BR	W	S 10	
104911	1	Guest BR	W	R 11	
104912	1	Garage	N	U 39	
104913	3	Master BR	S	I 71	
104914	3	Master BR	W	K 83	
104915	3	Master BR	E	H 78	
104916	3	Master BR	E	G 76	
104917	3	Master Bath	E	J 88	
104918	3	Hall	S	L 97	
104919	3	Hall Closet	S	M 99	
104920	3	Hall Closet	S	M 99 Dup	
104921	3	BR 1	E	P 102	
104922	3	BR 1	W	O 114	
104923	3	BR 1 Bath	S	N 116	
104924	1	1st Hall	N	XX	8x8

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Q-Trak/ Hobo

Client: _____

Home Address: (b)(6)

Field Person(s): _____

Date: 9/2/09
Project#: 16512

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
EIQT025	2	Living Room					9:20				Q-Trak
EIQT022	3	~~Guest~~ Master Bedroom					9:24				↓
EIQT029	1	~~Master~~ Guest Bedroom					9:26				↓
2412447	2	Living Room					9:35				Hobo
2412450	3	Master Bedroom					9:37				↓

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

090209VA01

PASSIVE SAMPLE FIELD DATA

Page _ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Date: 9/2

Client: _____ (b)(6)

Home Address: _

Project#: _____

Field Person(s): _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
✓ 104942	2	Living Room	NO_2 SO_2 HF	S	9/2	3:18	9/15	10:00	
✓ 104943	2	"		D					
✓ 104944	2	Outdoors		S					
✓ 104945	–	MB		–					
✓ 104946	1	Guest BR		S					
✓ 104947	3	Master BR		S					
~~104943~~									
~~104944~~									
~~104945~~									
~~104946~~									
~~104947~~									
✓ 104948	2	Living Room	Ozone	S	9/2	3:23	9/15	10:00	
✓ 104949	2	"		D					
✓ 104950	2	Outdoors		S					
✓ 104951	–	MB		–					
✓ 104952	1	Guest BR		S					
✓ 104953	3	Master BR		S					
~~104954~~									

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

090209VA01

PASSIVE SAM _E FIELD DATA

Page _ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Date: 9/2

Client: (b)(6)

Home Address:

Project#:

Field Person(s):

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
104930	2	Living Room	H_2S	S	9/2	3:07	9/15	10:00	
104931	2	"		D					
104932	–	MB		–					
104933	2	Outdoors		S					
104934	1	Guest BR		S					
104935	3	Master BR		S					
104936	2	Living Room	Aldehydes	S	9/2	3:13	9:15	10:00	
104937	2	"		D					
104938	–	MB		–					
104939	2	Outdoors		S					
104940	1	Guest BR		S					
104941	3	Master BR		S					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

090209VA01

PASSIVE SAMPLE FIELD DATA

Page _ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Coupons

Date: 9/2

Client: _____

Home Address: (b)(6)

Project#: _____

Field Person(s): _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES Coupon # / Tracking #
104925	2	Living Room		S	9/2	3:01 PM	9/15	10:00	63402 / 02504
104926	2	Out doors		S	↓	↓	↓	↓	63405 / 02504
✓ 104927	1	Guest BR		S	↓	↓	↓	↓	63399 / 02504
✓ 104928	3	Master BR		S	↓	↓	↓	↓	63395 / 02504
104929	1	1st Hall - Supply Air Diffuser		S	↓	↓	↓	↓	63398 / 02504

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ (b)(6)

Home Address: _____

Field Person(s): _____

Date: 9/2

Project#: _____

Camera ID: _____

PHOTO NO.	FLOOR	LOCATION	NOTES
440		Front of Home	
441		Address #	
442		Down stairs Bath (1st Floor)	
443		"	
444		Behind Toilet	
445		Air Handler Product Info	
446		"	
447		"	
448		Coolant Line	
449		Hot Water Heater Product Info	
450		"	
451		Water Pipes to Hot Water Heater	
452		Air Handler Coils	
453		"	
454		"	
455		"	
456		Back of Dry Wall	
457		"	
458		"	
459		Front of Fridge	
460		Fridge Coils	
461		"	
462		Air Handler Unit (attic)	
463		Product Info	
464		"	
465		"	
466		"	
467		"	
468		"	
469		"	

over

JFY

PHOTO FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: _____ (b)(6)

Home Address: _____

Field Person(s): _____

Date: 9/2

Project#: _____

Camera ID: _____

PHOTO NO.	FLOOR	LOCATION	NOTES
468		Air Handler Product Info (attic)	
469		"	
470		Air Handler Coolant Line (attic)	
471		Air Handler Coils (attic)	
472		"	
473		"	
474		"	