

Transmitted by email

July 26, 2024

Tek Lentine Chair, Technical Committee (TC) 60335-2-40 - Heating and Cooling Equipment – Heat Pumps, Air Conditioners and Dehumidifiers UL Standards & Engagement 1603 Orrington Ave # 2000 Evanston, IL 60201

Dear Tek:

As a follow-up to the June 4, 2024 letter I sent regarding incidents with room air conditioners falling out of windows, I am providing the attached table summarizing relevant data found in a search of the Consumer Product Safety Risk Management System (CPSRMS) database for incidents occurring within the timeframe 7/1/2014 through 6/30/2024 based on reports received as of 6/30/2024, using the product code for Room Air Conditioners (0381).¹ If you have any questions, please contact me at <u>atrotta@cpsc.gov</u>.

Thank you for your continued consideration of this issue.

Sincerely,

Andrew Trotta Director Division of Electrical Engineering and Fire Sciences Directorate for Engineering Sciences

Enclosure: Excel Spreadsheet titled AC_window_falls_UL_July_2024_EXTERNAL

U.S. Consumer Product Safety Commission 4330 East-West Highway Bethesda, MD 20814 National Product Testing & Evaluation Center 5 Research Place Rockville, MD 20850

¹ This letter was prepared by the CPSC staff. It has not been reviewed or approved by, and may not represent the views of, the Commission.



CC: Randy Cooper, Association of Home Appliance Manufacturers Jacqueline Campbell, CPSC Voluntary Standards Coordinator

U.S. Consumer Product Safety Commission 4330 East-West Highway Bethesda, MD 20814 National Product Testing & Evaluation Center 5 Research Place Rockville, MD 20850